# PUBLIC SAFETY FACILITY ASSESSMENT

TOWN OF WESTMINSTER, MA

**MARCH 2019** 













### CONTENTS

E	EXECUTIVE SUMMARY	,
E	XISTING FACILITY ASSESSMENT	2
	Architectural Narrative11	
	Exterior12	
	Interior	
	Structural Narrative25	
	MEP Narrative33	
	Fire Protection34	
	Plumbing36	
	HVAC38	
	Electrical39	
F	POLICE STATION PROGRAM	3
	Space Needs Assessment43	
	Room Summary47	
	Site Requirements68	
	Diagram69	
F	FIRE STATION PROGRAM	4
	Space Needs Assessment73	
	Room Summary75	
	Site Requirements89	
(	COMBINED PUBLIC SAFETY PROGRAM	5
	Space Needs Assessment93	
	Room Summary98	
	Site Requirements132	
	Diagram133	
(	OPINION OF PROBABLE COSTS	. 6
_	STILIZED EN VA AMARIES	-
- 6	TIDADAA PY ( IE PENIII IN	

## EXECUTIVE SUMMARY



#### **EXECUTIVE SUMMARY**

In January of 2019, working with Colliers International, the Owners' Project Manager, Tecton Architects, P.C. was contracted to conduct a facilities assessment of the existing Public Safety Facility in the Town of Westminster, MA. Additionally, a space needs assessment was conducted for a new Police Station, new Fire Station and a third possibility of a new joint Public Safety Facility. From the space needs assessments, an opinion of probable costs for each scheme. The purpose of this study was to assist the Town of Westminster in determining whether the existing facility could be renovated to accommodate one or both facilities or if a new facility would need to be constructed on a different site.











#### STUDY PROCESS

Tecton Architects, P.C. conducted separate interviews with both the Police, and Fire Departments. In those meetings Tecton, and Pacheco Ross Associates (PRA), Tectons' fire station programming consultant, met with each Chief and key personnel to review the following:

- Current department staff
- Future staff projections
- Current town population
- Future town population projections
- Current issues with the existing site
- · Current issues with the existing facility
- How the current facilities function
- · How the facility would ideally function in the future
- Opportunities for spaces that can be utilized for training
- · Safety and Security
- Parking and site features

From this information Tecton reviewed each potential space that is currently utilized in similar sized departments. That information assisted the development of the programs found in this document.

Once the programs were established an opinion of probable costs (OPC) was developed for each scheme utilizing current market data to assign costs per square foot for each facility, and escalated to the assumed mid-point of construction, based on the included schedule.

In addition to the programming of the new facilities Tecton in association with Consulting Engineering Services (CES), the MEP engineer, and Johnson Structural Engineering, (JSE), the structural engineer, an existing facility assessment was conducted. The purpose of this study was to understand the value of the existing building and what modifications would be required to have the existing facility comply with the current building code. It should be noted that where mechanical systems are listed as 'nearing the end of their usable life' that ASHRAE 90.1 identifies that MEP systems have an assumed life expectancy of 30-50 years. With that assumption, most of the MEP systems may begin to fail as soon as the next 5 years.

This information was then assembled into this document for the Town of Westminster's' use in moving forward with the construction and / or renovation based on the recommendations outlined in this study.

## EXISTING FACILITY ASSESSMENT ARCHITECTURAL NARRATIVE



#### **EXISTING BUILDING**

#### Location

7 South Street Westminster, MA 01473 Tax map ID 110//99// Zoned - R1

#### Site

- Size Approximately 4 acres divided between both Public Safety and Town Hall
- Public Safety portion of the site = 1.6 acres before factoring wetlands and setbacks.
- Setbacks per Zoning 205 Attachment 2 are as follows:
   Front = 25', Rear = 20', Side = 15'
- Parking 42 Spaces

#### **Building Description**

- Use Group B Business
- Construction Classification 5B Combustible Unprotected
- Wood framed with wood trusses
- Fire Suppression Yes
- Area 11,182 Gross Square Feet
- Stories 2, no basement
- Max Allowable Height per Zoning 205 Attachment 2 (2-1/2) Stories at 35'-0",
- Actual height of existing building at 45'-0"+/-
- First constructed during the 1950s with an addition in the late 50s and renovated to the current status in 1995.
- Floor to floor between ground level and upper level = 12'-4"
- Portions of the Town Halls' third floor are currently utilized to provide the Police Department with their records storage.



#### **EXTERIOR**

#### SITE

Current size utilization is near 100%, with little or no possibility to expand the facility. The existing building is on a municipal lot that was subdivided when the new Town Hall was constructed. The existing public safety facility is flanked by parking and drive aisles to the South and East and a return / response drive for the Fire Department to the Northwest. The North and West sections of the site are cut off from future development due to an active stream, and sections of the building, and out buildings, appear to currently be within, or close to the 25' buffer required from wetlands by the Conservation Commission bylaws (002 / 003). This would make alterations to these sections of the site and building difficult without a variance. Snow storage is also limited by the stream and shape of the site. It has also been reported by the department that there has been a history of the stream overflowing its bank bringing the high water line into the existing apparatus bays.

Bituminous pavement and concrete aprons for the apparatus bays are deteriorating, and will likely need replacement in the next 5 years (001). Parking is also not adequate to serve this facility. Currently, visitor parking is limited to a couple of spaces adjacent to the visitor entrance, if those are occupied then visitors will need to park closer to Town Hall, forcing them to walk across the Fire Department apron. This is not a preferred arrangement and is a potential hazard (004).

The presence of hazardous materials was not confirmed as part of this study. It is recommended that a Phase I Environmental Study be conducted to determine if hazardous materials are present.

Tecton received and reviewed the construction documents from the 1995 addition / renovation by Haynes Lieneck and Smith, Inc. Architects. Drawing A1 provides data from the geotechnical boring logs. The borings indicate a consistent water table between 4'-0" & 5'-0" below existing finish grade. Additionally, organics including peat, and degrading wood and roots were encountered up to 8'-0" below the existing finish grade. Should any additions or new buildings be constructed on this site a thorough geotechnical analysis should be conducted to determine what is required to provide adequate bearing capacity. With the elevated water table and adjacent stream, it may not be feasible to remove and replace this existing material with structural fill. The soil may require stabilization by installing a combination of grouted aggregate piers (GAPs) and rammed aggregate piers (RAPs), or by driven piles. It should be noted, however, that the existing building does not show signs of damages related to uneven settling.











#### BUILDING

#### Roof

Sloped roofs - 3 tab shingles, age of the roof was not verified, but there is one layer installed and on a visual inspection would be approximately 75% through its replacement cycle.

Flat / low slope roof - EPDM membrane roofing system - Small portion over the existing Sally port. Roof condition could not be verified due to snow cover. It was noted that the intersection with exterior wall has an issue with persistent leaking. This is likely caused by either deterioration or improper installation of the wall flashing.

Most of the building does not have storm-water controls from the roof, such as gutters and downspouts. The few that are installed on the building are either damaged, or draining towards the building instead of away. These should be repaired or replaced and the areas that do not have gutters should have them added.

#### Fascia and Trim

Roof edge trims, such as fascias and frieze boards are aluminum wrapped wood. Other trims and soffits are vinyl. Most of this material is in fair condition, with only specific areas requiring repair from either impact damages or mold and mildew propagation (005 / 006).

#### **Windows and Doors**

Windows - Vinyl double hung with 7/8" insulated glazing with simulated divided lites. Appears to be residential grade. U-value could not be confirmed, but is likely not in conformance with the current energy code.

Man Doors -Hollow metal with single glazed lites. Minimal rust was evident. Likely do not meet the current energy code, but are in generally good condition.

Overhead Doors Vinyl or Aluminum sectional overhead doors. Doors at the apparatus bays have lites in the third panel from the bottom. Could not verify if the over-head doors are insulated or if they meet the current energy code. The finish is wearing slightly and multiple bottom panels do not match the rest of the doors as they appear to have been previously damaged (007). Door bottom seals and weatherstripping does not appear to be functioning as intended and requires replacement. Only the 2 central apparatus bay overhead doors are adequate in size, standard size for an apparatus bay overhead door is 14'-0" x 14'-0".













#### Siding

Siding is generally in poor condition. Specific areas require repair from impact damages (008 / 009). Other locations, specifically on the North side of the building where sun exposure is limited, mold and mildew has propagated and needs to be cleaned (010 / 011).

#### **Envelope**

It was verified that the attic is currently insulated with approximately 6" of blown in cellulose insulation. At an average aged R-value of 3.5r/inch the total assumed R-value is an R21. The minimum required by the energy code is R-38, which is a 45% increase. If additional insulation is added to bring the envelope to the current code additional structure and bracing will need to be added (refer to structural report found later in this document). Wall insulation was not able to be identified. On the original building it was evident that a layer of 1/2" poly-iso rigid insulation was installed prior to the vinyl siding, and the existing drawings from the 1995 addition identify 6" fiberglass insulation. In addition to the insulation, it could not be verified if a code compliant air vapor barrier and / or vapor retarder are installed on either the original building or the addition, although the 1995 drawings also indicate that a vapor barrier is installed on the interior face of the framing behind the gypsum board. These will need to be verified and/or brought up to the current building & energy code should the building be renovated.

#### **POLICE DEPARTMENT**

#### **Hazardous Material Concerns**

It is noted on the most recent renovation addition drawings from 1995 that new gyp-sum ceilings were to be installed over existing (ACM). Based on this information we are to assume that asbestos containing material (ACM) is present in the building and will be required to be abated as part of either a renovation/addition or for the complete demolition of the existing building. There may also be additional encapsulated hazardous materials in the building, as well as damp-proofing under the slab and in the exterior walls as well. It is recommended that a hazardous material survey be conducted to confirm if these materials are present and what the process to abate will be.

#### **Code / ADA Concerns**


Several doors do no have ADA (Americans with Disability Act) compliant push/pull clearances. The facility currently has a Limited Use Limited Accessibility (LULA) Lift installed in lieu of an elevator. Inside the elevator machine room there is a 521 CMR (Architectural Access Board Guidelines) variance letter. With a renovation/addition, this will not suffice as a compliant method of vertical accessible circulation and a modern elevator and machine room will need to be installed that is in compliance 524 CMR (Massachusetts State Elevator Code) (012 / 013). Current stairs between the training room, police offices and the fire department do not have areas of rescue either. In order for this facility to be ADA compliant, accessible means of egress must be installed.

#### **Booking and Cells**


There is currently only a single cell. The cell is directly off of the booking room and does not have compliant sight sound separation. Also, the penal toilet sink combo is not an ADA compliant fixture. The diffusers for the HVAC system to the cell appears to be MaDPH 105 CMR (Massachusetts Department of Public Health Regulations) compliant. The requirement is that the perforations are no larger than 1/8". The ceilings are low, approximately 8'-6". It is recommended that ceilings in the cells are kept to a minimum of 10'-0". We were not able to determine if the existing HVAC system comply with MaDPH requirements for air hourly air changes while a person is detained (014 / 015).

The booking area is functional and adequately sized. The biggest concern in this space is the millwork. All of the counters and cabinets are plastic laminate over particle board. The adhesive has begun to break down over time and is causing the finish to de-laminate. This material is very rigid and sharp, and should a detainee get a hold of a piece of this material, it can be used as a weapon to either harm oneself or the attending office (016 / 017).














#### **Dispatch**

The space is very small for a similarly sized dispatch center. Consoles are against the wall in the corner and do not allow for direct visual access to the public at the lobby. Storage is limited. Public facing walls and windows are not bullet resistant. Finishes are in fair condition, but because of the layout of the space the department has reported that cleaning is an issue (018 / 019). There is also no central vacuum system installed. Since this continually operated it is recommended that a central vacuum system be utilized to reduce noise while cleaning and cut down on distractions to the dispatchers.

The current design of the dispatch center is also not NFPA 1221 compliant (Standards for the installation, maintenance, and use of emergency services communication systems). While this is not required by the building code, this is a recommended standard for dispatch facilities. Current deficiencies with this facility would include but are not limited to, 2 hour fire separation of the dispatch center and communications equipment (server/IT) from the rest of the building, the building being of non-combustible construction, and direct egress for the dispatchers to the exterior of the building. The construction of the current building will not allow for this facility to be compliant with this standard.

#### **SHARED FACILITIES**

#### Lobby

The lobby is generally small and connects both police and fire administration. There is a single small conference room that will seat 6-8. There are (2) single hold restrooms, male and female. A concern with the layout of the lobby is that it has several locations where a person can conceal themselves from direct view of the dispatchers which is a potential safety concern for staff.


#### **Training Room**

The existing training room is in good condition. Technology upgrades would be necessary. The ceiling height for the size of the room is too low for adequate displays. If this space was to be renovated for use as a modern training room and Emergency Operations Center (EOC), additional monitors should be placed around the perimeter and power and data floor boxes should be installed under the tables (020 / 021).

#### **Fitness**

Fitness Room is small for the size of the department. Flooring is broadloom carpet, which is not appropriate for sanitation or reducing sound transfer to the floor below. Locker facilities are small and do not provide adequate personnel storage (22 / 23).





018 019





020 021





022 023

The apparatus bays are in fair condition. The slab is called out as 6" concrete per the 1995 addition drawings with no radiant flooring. For modern loads imposed on these slabs is it preferred that an 8" slab with radiant flooring be provided (024). The transitions between the slab and the apron are deteriorating, causing cold air and water to infiltrate under the overhead doors (025). Floor drainage is undersized. Typically 24'-0" long trench drains should be installed on center between each bay rather than single 4" round drains (027).

Storage for the department is an issue. Currently, items that should be stored in separate rooms are stored in racks within the bays (026). In addition to storage, the adjacencies to the bays is a health issue. Break and kitchen areas, the day room and bunks are all directly off of the apparatus bay without a transition zone. Best practices require a transition zone where hazardous particles can be removed from clothing when going from the 'hot zone' to the 'cold zone'. There should also be positive pressure from cold to hot as well to prevent the spread of containments. This is a necessity in new fire station design to reduce the exposure to toxic chemicals and debris.

The rest of the fire facility is undersized. Most rooms serve multiple purposes, where they should only serve one. As an example, the day room also has EMS storage for the within it. The bunk room is only a single room with 2 beds, making it awkward for male and females to serve on the same 24 hour shift.

Finishes are in poor condition. Many are close to the end of their usable life and should be replaced with more durable finishes that will withstand the additional abuse they receive as a result of the nature of how firefighters conduct their daily business.






024 025





026





028 029

#### **SUMMARY**

The existing building has many critical deficiencies for a modern public safety building. It is significantly undersized for the sizes of these departments and their functions. The fire, police and dispatch functions are not designed to meet current standards for safety and functionality. The buildings structure is significantly deficient. Many of the interior and exterior finishes are near the end of their usable life. There is the presence of hazardous materials in the building, both in the finishes and due to the lack of separation of the apparatus bays and the rest of the facility. Based on these findings and of those under the MEP and structural reviews found later in this report it is our recommendation that it is practically infeasible for this building to be renovated and/or added on to in a way that it would appropriately serve its function.

## EXISTING FACILITY ASSESSMENT STRUCTURAL NARRATIVE



#### STRUCTURAL NARRATIVE

February 4, 2019

Tecton Architects
One Hartford Square West
Hartford, CT 06106
Attn: Matthew Salad

Re: Structural Review

Westminster Public Safety Complex

South Street Westminster, MA


Dear Mr. Salad:

As per your request, Johnson Structural Engineering (JSE) has performed a structural review of the existing Westminster Public Safety Complex. The structural review included a visual inspection of the exposed building structure and a structural code review to identify the structural implications of future alterations, renovations, and a potential addition. The following report summarizes the results of the structural review.

#### **Existing Condition**

Travis Alexander of JSE performed a site visit at the Westminster Public Safety Complex on January 22, 2019 to visually inspect the existing building structure. Please note that the inspection was limited to the existing structure that was accessible at the time of the site visit. The building is comprised of the original two-story structure, which houses the Police Department, and an addition that was constructed in 1995-1996, which houses the Fire Department. A majority of the structure is concealed by hard ceilings. The roof structure for the original building is comprised of wood trusses that are spaced at 2'-0" on center (o.c.) (see photograph #1). The second floor framing were not accessible during the site visit. It is likely that the second floor structure is comprised of wood joists that are supported by dropped beams and steel columns (see photograph #2). It is assumed that the dropped beams are steel W-shape beams. There are numerous CMU partition walls that stop just below the hard ceiling and are not anchored to the floor structure above (see photograph #3). The first floor is a concrete slab-on-grade. Numerous hairline cracks were observed along the concrete slab in the mechanical room of the Police Department (see photograph #4). It appears that the concrete slab is not properly sloped in the garage bay at the Police Department due to standing water that was observed during the site visit (see photograph #5). It is assumed that the existing exterior walls and full height interior masonry walls that align floor to floor act as shear walls, and therefore comprise the lateral system of the building.

A set of the original architectural drawings from the 1995 Fire Department addition were provided to your office during the site visit. The drawings were prepared by Haynes Lieneck and Smith Inc. and dated February 23, 1995. The drawings indicate that the roof structure for the addition is comprised of plywood sheathing supported by wood trusses that are spaced at 2'-0" o.c. The second floor structure is comprised of plywood



1 - Roof Structure - Police Department



2 - Second Floor Structure - Police Department

sheathing supported by wood trusses that are spaced at 2'-0" o.c. The roof framing and second floor framing are supported by 2x6 wood stud bearing walls along exterior and interior bearing lines. It is assumed that the existing exterior and interior wood stud walls that align floor to floor act as shear walls, and therefore comprised the lateral system of the building.

#### Structural Code Review

The International Existing Building Code 2015 (IEBC) and the 9th Edition of the Massachusetts State Amendments to the International Building Code 2015 (780 CMR) were reference for the structural code review.


For the purpose of the structural code review, it is assumed that the entire building will be involved in alterations and renovations. Since the work area exceeds 50 percent of the building area, the proposed alterations and renovations are classified as Level 3 Alternations (IEBC Section 505). The structural requirements provided in IEBC Chapter 9 must be satisfied for Level 3 Alterations.

#### **Gravity System**


The second floor area in the Police Department is currently used as office space. It is likely that the alterations and renovations will not result in a change of use for the space or impose any additional load onto the existing second floor framing (IEBC Section 907.3). In order to verify the live load capacity of the existing second floor structure, selective demolition will need to be performed in order to expose the framing members.

The second floor area in the Fire Department is currently used as a training room. It is likely that the alterations and renovations will not impose any additional load onto the existing second floor framing or result in an increase in the live load (IEBC Section 907.3). In order to verify the live load capacity of the existing second floor wood trusses, selective demolition will need to be performed to expose the trusses. Please note that the second floor structure for the addition was likely designed for 100 pounds per square foot (psf) for assembly space with moveable seats per the 5th Edition of the Massachusetts State Building Code from when the 1995 addition was originally designed.

It is JSE's recommendation that the R-value of the insulation in the attic space for both the original building and the 1995 addition is not increased over the R-value of the insulation that currently exists. An increase in the R-value of the attic insulation will result in less heat loss through the attic and roof structure. The heat loss helps to melt any built-up snow on the roof. If there is less heat loss through the attic and roof structure, then there could be more snow build-up on the roof. A structural analysis will need to be performed to verify the snow load capacity of the existing roof trusses that frame the roof over the original portion of the building. It is likely that the roof structure for the 1995 addition were designed for a 35psf snow load per the 5th Edition of the Massachusetts State Building Code. Please note that the current 780 CMR design snow load for "essential facilities" located in Westminster, Massachusetts is 50.4psf.



3 - CMU walls to underside of hard ceiling - Police Department



4 - Concrete slab-on-grade hairline cracks - Police Department



5 - Standing water in Sally Port - Police Department

#### **Lateral System**

As previously stated, it is assumed that the existing exterior walls and full height interior masonry walls that align floor to floor in the original building and the existing exterior walls and interior bearing walls of the 1995 addition act as shear walls, and therefore comprise the lateral system of the building. If the proposed alterations and renovations result in new openings within the existing shear walls or the demolition of any existing shear walls which increases the demand-capacity ratio for the existing shear walls that are to remain by more than 10 percent, then the existing shear walls that remain will need to be reinforced accordingly. Typical reinforcing will likely include additional hold-downs and/or straps at the ends of the shear walls and plywood sheathing. Please note that the current design wind load and seismic force are greater than those specified in the 5th Edition of the Massachusetts State Building Code from when the 1995 addition was designed.

Wall ties must be installed to anchor all existing masonry walls to the floor and roof diaphragms (IEBC Section 907.4.5).

#### **Addition**

If any new additions are proposed as part of the alterations and renovations to the existing building, then the structural design of the addition must comply with the gravity and loads specified in the International Building Code 2019 for new construction and the requirements specified in IEBC Chapter 11. Any new additions must be kept structurally separated from the existing building in order to avoid imposing any additional lateral load into the lateral system of the existing building. If the addition imposes any snow drift onto the existing roof structure, then the existing roof structure will need to be reinforced accordingly.

If you have any questions regarding this report, please do not hesitate to call.

Sincerely Yours, Johnson Structural Engineering, Inc.

Robert A. Johnson, P.E. President

# EXISTING FACILITY ASSESSMENT MEP NARRATIVE



#### **EXISTING FIRE PROTECTION SYSTEM**

1. The building currently has a fully automatic wet sprinkler system installed throughout the whole facility. The fire protection service enters the Apparatus Buy and piping is routed to feed all spaces in the building. This service is 8" from the site into the building and then reduced to 4" inside the building. All piping was observed to be steel with mechanical and screwed fittings. This system appears to have been installed in the 1995 renovation and is nearing the end of its useful life. (FP-1)



FP-1

#### **PLUMBING NARRATIVE**

#### **EXISTING PLUMBING AND PIPING SYSTEMS**

- Domestic Water Service: The domestic water service enters the building in the Apparatus Bay. The water service to the building is 4" and reduces to 2 ½" inside. The service and meter appears to have been installed in the 1995 renovation and is nearing the end of their useful life. (P-1)
- 2. Domestic Water Piping: The domestic water piping in the building was observed to be copper with soldered joints. This piping appears to have been installed in the 1995 renovation and is nearing the end of their useful life.
- 3. Natural Gas Service: The natural gas service enters the building on the north side of the building. Natural gas piping was observed to be steel with welded and threaded joints. This gas service appears in good condition but appears to have been installed in the 1995 renovation and is nearing the end of its uses full life. The natural gas service feeds the boilers and water heaters. (P-2)
- 4. Sanitary and Storm: The building's sanitary and storm piping was observed to be cast iron and copper. All piping's appears to have been installed in the 1995 Renovation and at the end of its useful life. There is no internal storm drainage piping as all storm is handled with gutters and downspouts on the edge of the roof.
- 5. Domestic Hot Water System: Domestic water is currently generated by a single gas fired Water Heater. The heater is a Rheem 82 Gallon Tank with an input of 156,000 BTUH. The tank was manufactured in 2010 and is in good condition. (P-3)



P-1





P-2 P-3

#### MECHANICAL NARRATIVE

#### **MECHANICAL SYSTEMS**

#### **Existing Boiler Plant**

1. The existing boiler plant consists of three (3) boilers. One boiler feeds the Fire Department side while the other feeds the Police Department Side. The first boiler feeds the Fire Department side and is a natural gas Burnham Boiler rated at 800,000 BTUH input. (M-1) This boiler appears to have been installed in the 1995 renovation and is nearing the end of its useful life. The other two (2) boilers are natural gas fired Peerless Boilers rated at 200,000 BTUH input each. (M-2) These boilers were installed around 2006 and are in good working condition.

#### Existing Heating, Ventilating, and Air Conditioning Devices

- 1. The building is currently heated through the use of hydronic baseboard radiation, electrical baseboard radiation, hydronic fan coils and hydronic unit heaters. The age of the terminal devices varies for original to the building to the 1995 renovation. (M-3) The majority of all terminal units were installed in the 1995 renovation. With the different ages of the equipment most are nearing the end of their useful life while some are past their useful life. Piping serving all terminal devices was observed to be a combination of copper and steel. This piping was also installed in the 1995 renovation and is nearing the end of its useful life.
- 2. Exhaust from bathrooms, storage rooms and janitor's closets are achieved through the use of ceiling mounted exhaust fans. The fans are ducted to the outside with sheet metal ductwork. These fans were installed in the 1995 renovation and at the end of their useful life.
- 3. Air Condition in the facility was achieved through the use of Ductless Split Air Conditioners. Air conditioning was limited to Second Floor Sever Room, Booking, Dispatch, Control and Bunk Rooms. Some of these air conditions are from the 1995 renovation and are at the end of their useful life while a couple have been put in within the last few years. (M-4) All other areas that had air conditioning were from window mounted packaged Air Conditioners.
- 4. The apparatus bay is currently served by an exhaust system that ventilates the bays. This system brings 100% outside air into the south side of the bays and exhausts it on the north side of the space. The trucks in this space are also served by a vehicle exhaust system that attaches the exhaust outlets of the vehicles. (M-5) While these systems meet the codes they require a lot of exhaust air that needs to be heated and is not very energy efficient. These systems appear to be have been installed in the 1995 renovation and are nearing the end of their useful life.







M-2



M-1





M-4 M-5

# **ELECTRICAL NARRATIVE**

#### **ELECTRICAL SYSTEMS**

#### **Electrical Service and Distribution:**

- Electrical services: The service to this building is a 208Y/120V 3 phase, 400
   Amps underground feed. It terminates at a main distribution panel in the Main
   Electrical Room of the Building. The main distribution panel is manufactured by
   Siemens and was installed in the 1995 Renovation. This panel is nearing the end
   of its useful life. (E-1)
- 2. Electrical distribution: The electrical infrastructure of this building received a major overhaul in 1995. At this time the new addition was provided with a complete new electrical distribution system. The original portion of the building was back fed from the new service and the majority of the original wiring and panels were existing to remain. The wiring that is original is past its useful life and the wiring that was installed in the 1995 renovation is nearing the end of its useful life.

# **Existing On Site Power Generation System**

1. The building is currently served by an onsite diesel generator. The generator is manufactured by Kohler and rated for 60 KW. This generator serves backup for major components in the building but is not for life safety items. (E-2)

# **Existing Fire Alarm System**

1. Fire Alarm Panel: The building is equipped with a Notifier System 5000 Fire Alarm Control Panel located at the electrical room. This panel is at the end or its useful life and is not addressable.





F-1 E-2

# **Interior Lighting**

- 1. Lighting is accomplished by the use of 1'x4', 2'x2' and 2'x4' Fluorescent fixtures, with T8 lamps. These fixtures were installed in the 1995 renovation and are at the end of their useful life. (E-3)
- 2. Lighting fixtures are generally controlled by wall mounted toggle switches. No occupancy sensor and daylight control devices were observed in the building, with the exception of a few combination switch/sensors that have been added.

# **Exit Signs and Emergency Lighting**

- 1. Emergency Lighting: Emergency lighting is provided via an emergency lighting battery packs located in the fixtures of the building.
- 2. Exit signs within the building are of mixed type. Most of the signs are aged and at the end of their useful life.

# **Exterior Lighting**

1. Exterior lighting is currently accomplished by building-mounted wall packs mounted on the perimeter walls of the building.



# POLICE STATION PROGRAM



# Westminster, Massachusetts Space Needs Summary

1.   Public   80 s.f.	lew Prog	rammed Area Name		Program Area
1.01   Vestibule				
1.02				80 s f
1.03	- 1			
1.04   Male Restroom   160 s.f.   160 s.f.	- 1	•		
Subtotal: 1010 s.f.	- 1			160 s.f.
2. Dispatch Center       450 s.f.         2.02 Dispatch Supervisor       120 sf         2.03 Unisex Restroom       65 s.f.         2.04 Comm Eq. / IT       200 s.f.         2.05 Break Area       135 s.f.         Subtotal: 1105 s.f.         3.01 Records Archive         3.02 Central Photocopy       50 s.f.         3.03 Office Supply Storage       10 s.f.         4 . Community/Training Room         4.01 Training Room       1360 s.f.         4.02 Supply Storage       25 s.f.         4.03 Furniture Storage       100 s.f.         4.04 Kitchenette       20 s.f.         Subtotal: 1505 s.f.         5 Patrol Facilities         5. Patrol Facilities       240 s.f.         5.01 Sergeants       240 s.f.         5.02 Patrol Conference       150 s.f.         5.03 Report Preparation/Squad Room       200 s.f.         5.04 Quartermaster Storage       80 s.f.         5.05 Weapons Cleaning       40 s.f.         5.06 Armory       40 s.f.		1.05 Female Restroom		160 s.f.
2.01   Dispatch Center   450 s.f.			Subtotal:	1010 s.f.
2.02   Dispatch Supervisor   120   sf   2.03   Unisex Restroom   65   s.f.   2.04   Comm Eq. / IT   200   s.f.   2.05   Break Area   135   s.f.   Subtotal:   1105   s.f.   Subtotal:   1105   s.f.   Subtotal:   1105   s.f.   3.0   Records Archive   120   s.f.   3.02   Central Photocopy   50   s.f.   3.03   Office Supply Storage   10   s.f.   Subtotal:   180   s.f.   Subtotal:   180   s.f.   Subtotal:   180   s.f.   4.   Community/Training Room   1360   s.f.   4.02   Supply Storage   25   s.f.   4.03   Furniture Storage   100   s.f.   4.04   Kitchenette   20   s.f.   Subtotal:   1505   s.f.   5.0   Patrol Facilities   Subtotal:   1505   s.f.   5.02   Patrol Conference   150   s.f.   5.03   Report Preparation/Squad Room   200   s.f.   5.04   Quartermaster Storage   80   s.f.   5.05   Weapons Cleaning   40   s.f.   5.06   Armory   40   s.f.   5.06   Armory   40   s.f.	2.	Dispatch Center		
2.02   Dispatch Supervisor   120   sf   2.03   Unisex Restroom   65   s.f.   2.04   Comm Eq. / IT   200   s.f.   2.05   Break Area   135   s.f.   Subtotal:   1105   s.f.   Subtotal:   1105   s.f.   Subtotal:   1105   s.f.   3.0   Records Archive   120   s.f.   3.02   Central Photocopy   50   s.f.   3.03   Office Supply Storage   10   s.f.   Subtotal:   180   s.f.   Subtotal:   180   s.f.   Subtotal:   180   s.f.   Subtotal:   180   s.f.   4.   Community/Training Room   1360   s.f.   4.02   Supply Storage   25   s.f.   4.03   Furniture Storage   100   s.f.   4.04   Kitchenette   20   s.f.   5.   Patrol Facilities   Subtotal:   1505   s.f.   5.02   Patrol Conference   150   s.f.   5.03   Report Preparation/Squad Room   200   s.f.   5.04   Quartermaster Storage   80   s.f.   5.05   Weapons Cleaning   40   s.f.   5.06   Armory   40   s.f.   5.06   Armory   40   s.f.		2.01 Dispatch Center		450 s.f.
2.04   Comm Eq. / IT   200 s.f.   2.05   Break Area   135 s.f.   Subtotal:   1105 s.f.     3.0	- 1	•		120 sf
2.05   Break Area   135 s.f.   Subtotal:   1105 s.f.     3.0   Records   120 s.f.   3.02   Central Photocopy   50 s.f.   3.03   Office Supply Storage   10 s.f.   Subtotal:   180 s.f.     4.   Community/Training Room   1360 s.f.   4.02   Supply Storage   25 s.f.   4.03   Furniture Storage   100 s.f.   4.04   Kitchenette   20 s.f.   Subtotal:   1505 s.f.     5.   Patrol Facilities   Subtotal:   1505 s.f.   5.02   Patrol Conference   150 s.f.   5.03   Report Preparation/Squad Room   200 s.f.   5.04   Quartermaster Storage   80 s.f.   5.05   Weapons Cleaning   40 s.f.   5.05   Weapons Cleaning   40 s.f.   5.06   Armory   40 s.f.   5.06   Armory   40 s.f.   5.06   Armory   40 s.f.   5.07   40 s.f.   5.08   Armory   40 s.f.   5.09   Armory	- 1	2.03 Unisex Restroom		65 s.f.
Subtotal: 1105 s.f.   3.0   Records   120 s.f.   3.01   Records   Archive   120 s.f.   3.02   Central Photocopy   50 s.f.   3.03   Office Supply Storage   10 s.f.   Subtotal: 180 s.f.	- 1	2.04 Comm Eq. / IT		200 s.f.
3.01       Records Archive       120 s.f.         3.02       Central Photocopy       50 s.f.         3.03       Office Supply Storage       10 s.f.         Subtotal: 180 s.f.         4.       Community/Training Room       1360 s.f.         4.02       Supply Storage       25 s.f.         4.03       Furniture Storage       100 s.f.         4.04       Kitchenette       20 s.f.         5.       Patrol Facilities         5.01       Sergeants       240 s.f.         5.02       Patrol Conference       150 s.f.         5.03       Report Preparation/Squad Room       200 s.f.         5.04       Quartermaster Storage       80 s.f.         5.05       Weapons Cleaning       40 s.f.         5.06       Armory       40 s.f.	- 1	2.05 Break Area		135 s.f.
3.01   Records Archive   120   s.f.     3.02   Central Photocopy   50   s.f.     3.03   Office Supply Storage   10   s.f.     Subtotal:   180   s.f.     4.   Community/Training Room   1360   s.f.     4.01   Training Room   1360   s.f.     4.02   Supply Storage   25   s.f.     4.03   Furniture Storage   100   s.f.     4.04   Kitchenette   20   s.f.     Subtotal:   1505   s.f.     5.   Patrol Facilities     5.01   Sergeants   240   s.f.     5.02   Patrol Conference   150   s.f.     5.03   Report Preparation/Squad Room   200   s.f.     5.04   Quartermaster Storage   80   s.f.     5.05   Weapons Cleaning   40   s.f.     5.06   Armory   40   s.f.     5.07   Sergeaning   40   s.f.     5.08   Sergeaning   40   s.f.     5.09   Sergeaning   40   s.f.     5.01   Sergeaning   40   s.f.     5.02   Sergeaning   40   s.f.     5.03   Sergeaning   40   s.f.     5.04   Sergeaning   40   s.f.     5.05   Sergeaning   40   s.f.     5.06   Armory   40   s.f.     5.07   Sergeaning   40   s.f.     5.08   Sergeaning   40   s.f.     5.09   Sergeaning   40   s.f.     5.01   Sergeaning   40   s.f.     5.02   Sergeaning   40   s.f.     5.03   Sergeaning   40   s.f.     5.04   Sergeaning   40   s.f.     5.05   Sergeaning   40   s.f.     5.06   Sergeaning   40   s.f.     5.07   Sergeaning   40   s.f.     5.08   Sergeaning   40   s.f.     5.09   Sergeaning   40   s.f.     5.00   Sergeaning   40   s.f.     5.01   Sergeaning   40   s.f.     5.02   Sergeaning   40   s.f.     5.03   Sergeaning   40   s.f.     5.04   Sergeaning   40   s.f.     5.05   Sergeaning   40   s.f.     5.06   Sergeaning   40   s.f.     5.07   Sergeaning   40   s.f.     5.08   Sergeaning   40   s.f.     5.09   Sergeaning   40   s.f.     5.00   Sergeaning   50   s.f.     5.01   Sergeaning   50   s.f.     6.02   Sergeaning   50   s.f.     7.03   Sergeaning   50   s.f.     8.04   Sergeaning   50   s.f.     8.05   Sergeaning   50   s.f.     9.05   Sergeaning   50   s.f.     9.06   Sergeaning   50   s.f.     9.07   Sergeaning   50   s.f.     9.08   Sergeaning   50   s.f.			Subtotal:	1105 s.f.
3.02       Central Photocopy       50 s.f.         3.03       Office Supply Storage       10 s.f.         4 .       Subtotal:       180 s.f.         4 .       Community/Training Room       1360 s.f.         4.02       Supply Storage       25 s.f.         4.03       Furniture Storage       100 s.f.         4.04       Kitchenette       20 s.f.         5 .       Patrol Facilities         5.01       Sergeants       240 s.f.         5.02       Patrol Conference       150 s.f.         5.03       Report Preparation/Squad Room       200 s.f.         5.04       Quartermaster Storage       80 s.f.         5.05       Weapons Cleaning       40 s.f.         5.06       Armory       40 s.f.	3.	Records		
3.03 Office Supply Storage		3.01 Records Archive		120 s.f.
Subtotal: 180 s.f.	- 1	3.02 Central Photocopy		50 s.f.
4       Community/Training Room       1360 s.f.         4.02       Supply Storage       25 s.f.         4.03       Furniture Storage       100 s.f.         4.04       Kitchenette       20 s.f.         Subtotal: 1505 s.f.         5       Patrol Facilities         5.01       Sergeants       240 s.f.         5.02       Patrol Conference       150 s.f.         5.03       Report Preparation/Squad Room       200 s.f.         5.04       Quartermaster Storage       80 s.f.         5.05       Weapons Cleaning       40 s.f.         5.06       Armory       40 s.f.	- 1	3.03 Office Supply Storage		10 s.f.
4.01       Training Room       1360 s.f.         4.02       Supply Storage       25 s.f.         4.03       Furniture Storage       100 s.f.         4.04       Kitchenette       20 s.f.         Subtotal: 1505 s.f.         5.       Patrol Facilities         5.01       Sergeants       240 s.f.         5.02       Patrol Conference       150 s.f.         5.03       Report Preparation/Squad Room       200 s.f.         5.04       Quartermaster Storage       80 s.f.         5.05       Weapons Cleaning       40 s.f.         5.06       Armory       40 s.f.			Subtotal:	180 s.f.
4.02       Supply Storage       25 s.f.         4.03       Furniture Storage       100 s.f.         4.04       Kitchenette       20 s.f.         Subtotal: 1505 s.f.         5.       Patrol Facilities         5.01       Sergeants       240 s.f.         5.02       Patrol Conference       150 s.f.         5.03       Report Preparation/Squad Room       200 s.f.         5.04       Quartermaster Storage       80 s.f.         5.05       Weapons Cleaning       40 s.f.         5.06       Armory       40 s.f.	4 .	Community/Training Room		
4.03       Furniture Storage       100 s.f.         4.04       Kitchenette       20 s.f.         Subtotal: 1505 s.f.         5.       Patrol Facilities         5.01       Sergeants       240 s.f.         5.02       Patrol Conference       150 s.f.         5.03       Report Preparation/Squad Room       200 s.f.         5.04       Quartermaster Storage       80 s.f.         5.05       Weapons Cleaning       40 s.f.         5.06       Armory       40 s.f.		4.01 Training Room		1360 s.f.
4.04         Kitchenette         20 s.f.           Subtotal: 1505 s.f.           5 . Patrol Facilities           5.01         Sergeants         240 s.f.           5.02         Patrol Conference         150 s.f.           5.03         Report Preparation/Squad Room         200 s.f.           5.04         Quartermaster Storage         80 s.f.           5.05         Weapons Cleaning         40 s.f.           5.06         Armory         40 s.f.	- 1	4.02 Supply Storage		25 s.f.
5.         Patrol Facilities           5.01         Sergeants           5.02         Patrol Conference           5.03         Report Preparation/Squad Room           5.04         Quartermaster Storage           5.05         Weapons Cleaning           5.06         Armory           40         s.f.           40         s.f.	- 1	4.03 Furniture Storage		100 s.f.
5.         Patrol Facilities           5.01         Sergeants         240 s.f.           5.02         Patrol Conference         150 s.f.           5.03         Report Preparation/Squad Room         200 s.f.           5.04         Quartermaster Storage         80 s.f.           5.05         Weapons Cleaning         40 s.f.           5.06         Armory         40 s.f.	- 1	4.04 Kitchenette		20 s.f.
5.01       Sergeants       240 s.f.         5.02       Patrol Conference       150 s.f.         5.03       Report Preparation/Squad Room       200 s.f.         5.04       Quartermaster Storage       80 s.f.         5.05       Weapons Cleaning       40 s.f.         5.06       Armory       40 s.f.			Subtotal:	1505 s.f.
5.02 Patrol Conference 150 s.f. 5.03 Report Preparation/Squad Room 200 s.f. 5.04 Quartermaster Storage 80 s.f. 5.05 Weapons Cleaning 40 s.f. 5.06 Armory 40 s.f.	5.	Patrol Facilities		
5.03Report Preparation/Squad Room200 s.f.5.04Quartermaster Storage80 s.f.5.05Weapons Cleaning40 s.f.5.06Armory40 s.f.		5.01 Sergeants		240 s.f.
5.04Quartermaster Storage80 s.f.5.05Weapons Cleaning40 s.f.5.06Armory40 s.f.		5.02 Patrol Conference		150 s.f.
5.05 Weapons Cleaning 40 s.f. 5.06 Armory 40 s.f.	- 1	5.03 Report Preparation/Squad Room		200 s.f.
5.06 Armory 40 s.f.		5.04 Quartermaster Storage		80 s.f.
'		5.05 Weapons Cleaning		40 s.f.
Subtotal: 750 s.f.		5.06 Armory		40 s.f.
			Subtotal:	750 s.f.

# Westminster, Massachusetts Space Needs Summary

New Prog	grammed A	rea Name		Program Are	a
6.	Invest	ligative			
	6.01	Detective's Office x 2		280	s.f.
	6.02	Interview Room		100	s.f.
	6.03	Equipment Storage Room		12	s.f.
$\neg$		· · · · · · · · · · · · · · · · · · ·	Subtotal:	392	s.f.
7.	Depa	rtment Administration			
	7.01	Administrative Assistant		120	s.f.
	7.02	Reprographics/Work Area		20	s.f.
	7.03	Future Office		120	s.f.
	7.04	Lieutenant's Office		160	s.f.
	7.05	Chief's Office		180	s.f.
	7.06	Conference Room		320	s.f.
$\neg$			Subtotal:	920	s.f.
8.	Staff F	acilities			
	8.01	Male Restroom/shower		210	s.f.
	8.02	Male Locker Room		400	s.f.
	8.03	Female Restroom/shower		160	s.f.
	8.04	Female Locker Room		110	s.f.
	8.05	Break Room		180	s.f.
	8.06	Miscellaneous Male Restrooms		65	s.f.
	8.07	Miscellaneous Female Restroom		65	s.f.
	8.08	Fitness Center		500	s.f.
			Subtotal:	1690	s.f.
9.	Prope	rty and Evidence			
	9.01	Evidence Laboratory		150	s.f.
	9.02	Evidence Receiving		40	s.f.
	9.03	Evidence Storage		400	s f
!		LVIderice storage			J

Space Needs Summary

lew Prog	rammed Area Name		Program Area
10 .	Prisoner Processing		
	10.01 Sally Port (1-cruiser)		450 s.f.
	10.02 Processing Area		250 s.f.
	10.03 Holding Cell		50 s.f.
	10.04 Intoxilyzer Area		12 s.f.
	10.05 Custodial Closet		20 s.f.
	10.06 Interview Room		100 s.f.
_	10.07 Detention Restroom/shower		50 s.f.
- 1		Subtotal:	932 s.f.
11 .	Detention Facilities		
	11.01 Unisex Cells (x3)		400 s.f.
		Subtotal:	400 s.f.
12 .	Vehicle Storage		
	12.01 Vehicle Processing/Cruiser Maintenance		960 s.f.
	12.02 Mechanic's Storage		40 s.f.
		Subtotal:	1000 s.f.
13 .	Building Services		
	13.01 Custodial Closets x 1		20 s.f.
	13.02 Facility Maintenance Storage		80 s.f.
	13.03 Boiler Room		200 s.f.
	13.04 Sprinkler Room		50 s.f.
	13.05 Air Handling Equipment Room		TBD s.f.
	13.06 Electrical Room		80 s.f.
_	13.07 Emergency Electrical Room		60 s.f.
- 1		Subtotal:	490 s.f.
14 .	Vertical Circulation		
	14.01 Stair x 2 x 2-floors		800 s.f.
	14.02 Elevator x 2-floors		120 s.f.
	14.03 Elevator Machine Room		60 s.f.
		Subtotal:	980 s.f.

# **SPACE NEEDS ASSESSMENT**

# Westminster, Massachusetts Space Needs Summary

w Programmed Area Name	Program Area	
Summation		
Facility net area:	11,944 s.f.	
Net to gross adjustment (30%)	3,583 s.f.	
Facility gross area total:	<b>15,527</b> s.f.	

Detail Space Requirements

Police Station

Publi	
1.01	Vestibule 80 s
	<ul> <li>Security</li> <li>free access from exterior</li> <li>emergency lockdown of inner doors</li> <li>ballistic protection in any wall interfacing staff areas</li> <li>Electrical</li> <li>fire alarm annunciator panel</li> </ul>
1.02	Lobby 450 s
	<ul> <li>lobby design should reflect an environment of service to the community and visitors</li> <li>Security <ul> <li>free access with emergency lockdown provisions</li> <li>proximity access control to secure areas</li> <li>remote release of doors from dispatch desk</li> <li>ballistic protection in all walls interfacing staff areas</li> <li>audio/video monitoring</li> </ul> </li> <li>Furniture <ul> <li>waiting chairs</li> </ul> </li> <li>Equipment <ul> <li>public access computer terminals</li> </ul> </li> <li>Casework and built-ins <ul> <li>pamphlet/form rack for community information</li> <li>display cases</li> <li>drops for cell phone donations, prescription drugs, used needledisplay</li> </ul> </li> <li>Display <ul> <li>flat panel information monitor</li> <li>display cases for historic artifacts</li> <li>wall space for display of historic artifacts</li> <li>graphic Town map for visitor assistance</li> </ul> </li> <li>Mechanical <ul> <li>do not recirculate air into staff areas</li> </ul> </li> </ul>
	Plumbing
	1 drinking fountain (accessible)

Detail Space Requirements

Police Station

# New Programmed Area Name

Program Area

# Public Interview/Licensing Room - continued

#### Casework and built-ins

6 lineal foot licensing counter with cabinets below

#### Security

- proximity access control
- audio/video monitoring to record activities including probate child exchange, internet purchasing, etc.
- ballistic protection in walls interfacing staff areas
- panic device

#### **Furniture**

1 table w/ six chairs

# **Equipment**

- 1 computer on licensing counter
- 1 fingerprint station
- 1 wall telephone

### 1.04 Male Restroom

160 s.f.

# **Plumbing**

- 1 water closet
- 1 urinal
- 1 sink
- 1 floor drain with trap primer

# **Equipment**

- toilet accessories as required
- mirrors at sinks
- changing station

# Security

- ballistic protection in walls interfacing staff areas
- avoid concealed areas within room or above ceiling

#### 1.05 Female Restroom

160 s.f.

#### Plumbing

- 2 water closet
- 1 sink
- 1 floor drain with trap primer

# Equipment

- toilet accessories as required
- mirrors at sinks
- changing station

#### Security

- ballistic protection in walls interfacing staff areas
- avoid concealed areas within room or above ceiling

# Detail Space Requirements

Police Station

# New Programmed Area Name

Program Area

# 2. Dispatch Center

# 2.01 Dispatch Center

450 s.f.

#### **Description**

• Dispatchers serve as the public reception point.

#### **Acoustics**

- partitions to extend to underside of structure
- sound batt insul. in stud partitions
- acoustic wall panels on 20% of surface

#### **Furniture**

- 2 dispatch consoles with chairs
- 6 rolling two drawer lateral file cabinets (under counter)

#### Casework and Built-ins

- 10 I.f. open countertop
- 6 I.f. wall shelving over files (over counter)
- 4 I.f. upper cabinets (over counter)
- storage for "bug-out" bins

# **Equipment**

- 1 multifunction device (on casework)
- 1 logging recorder
- 1 scanner (on casework)
- 1 leaps computer terminal at counter
- central vacuum system
- note: equipment per console as indicated below:

# Console #1

- 2 911 monitor(s)
- 1 radio monitor
- 1 CJIS monitor
- 1 security monitor
- 1 TDD, text to 911, reverse 911
- 1 radio PD, FD and DPW
- 1 intercom
- 1 telephone

### Console #2

- 2 911 monitor(s)
- 1 radio monitor
- 1 CJIS monitor
- 1 security monitor
- 1 TDD, text to 911, reverse 911
- 1 radio PD, FD and DPW
- 1 intercom
- 1 telephone

Detail Space Requirements

Police Station

# New Programmed Area Name

Program Area

# Dispatch Center - continued

# Display

- 1 GPS vehicle location monitor
- 2 large flat screen perimeter/cell security monitors
- 1 flat screen television monitor
- 1 4'x6' marker board
- 1 4' x 6' tack board

# **Special Design Considerations**

raised access floor or directly over communications equipment room

#### Mechanical

dedicated hvac system

#### **Electrical**

- all systems on UPS and emergency generator
- indirect lighting with multilevel control

# Security

- proximity access control
- ballistic protection in walls interfacing public areas
- 2-hour fire separation
- ballistic window to lobby w/ natural voice transmission
- ballistic deal tray to lobby
- ballistic package passer

# 2.02 Dispatch Supervisors Office

120 s.f.

# Furniture

- 1 Small Dispatch console
- 3 two drawer lateral file cabinets
- 1 worktable with four chairs

#### Casework and Built-ins

- 9 If open countertop (over files)
- 18 If wall shelving (over files)

# **Equipment**

- 1 computer (@ workstation)
- 1 telephone (@ workstation)

### **Acoustics**

sound batt insul. in stud partitions

### Security

standard commercial lockset

**Detail Space Requirements** 

Police Station

New Programmed Area Name

Program Area

# Dispatch Supervisors Office - continued **Accessory Areas** coat closet **Equipment** 1 wall telephone 1 radio speaker 2.03 **Unisex Restroom** 65 s.f. Plumbing 2 water closet sink floor drain with trap primer 1 **Equipment** • toilet accessories as required mirrors at sinks changing station Security ballistic protection in walls interfacing staff areas avoid concealed areas within room or above ceiling 200 s.f. **Communications Equipment Room/IT** 2.04 Casework and Built-ins 6 lineal feet of open counter **Equipment** 1 electronic radio equipment racks network racks 1 security rack 1 911 racks 1 future rack 1 administrative computer 16 lineal feet of 8' high plywood backboard 1 telephone 1 logging recorder cable tray over racks Electrical • all systems on UPS and emergency generator 4 4" conduits from pole to communications equipment 4 4" conduit to antenna/microwave 2 future conduit to roof Fire Protection • pre-action fire suppression system

Detail Space Requirements

Police Station

# **New Programmed Area Name**

Program Area

# Communications Equipment Room / IT - continued Security • access from outside of dispatch proximity access control masonry wall construction or wire mesh in partitions • 2 hour fire rating **Break Area** 2.05 135 s.f. Furniture dining counter with two chairs Casework and Built-ins 8 lineal feet of base and upper cabinets **Equipment** 1 refrigerator 1 microwave 1 coffee machine 12 12" x 24" x 72" dispatcher lockers **Plumbing** 1 kitchen sink

# 3. Records

Display

3.0	Records Archive	120 s.f.
-	Furniture 72 lineal feet of high-density 5 high file store 4 three drawer lateral file cabinets	age
	Equipment 1 wall telephone	
	Security - proximity access control	
3.0	Central Photocopy	50 s.f.
	Casework and Built-ins 6 If base cabinets w/ countertop	
	Equipment  1 multipurpose machine 1 wall telephone(s)	
	Security  • none	

1 flat panel wall monitor with cable tv

Police Station

New Progr	New Programmed Area Name		Program Area
	3.03	Office Supply Storage	10 s.f.
		Casework and Built-ins 30 lineal feet of shelving on standards	

4.01	Training Room	1360 s.f.
	Occupants 50	
	<ul><li>General</li><li>may be used as emergency operations center</li></ul>	
	<ul> <li>Acoustics</li> <li>partitions to extend to underside of structure</li> <li>sound batt insulation in stud partitions</li> </ul>	
	Furniture 25 2'x6' tables with chairs 1 "smart" podium • center aisle and two side aisles	
	Casework and Built-ins 12 lineal feet base cabinets	
	<ul> <li>Equipment</li> <li>tel/data floor boxes for tables</li> <li>wall telephone</li> <li>lighting control panel</li> <li>Internal and external jacks for cable access television</li> <li>telephone line drops from ceiling</li> </ul>	n
	Display 2 4' x 6' marker board 2 flat panel monitors 4 4'x4' tack boards	
	<ul> <li>Security</li> <li>proximity access control</li> <li>interlock to switch control point</li> <li>ballistic protection in walls interfacing staff areas</li> </ul>	
4.02	Supply Storage	25 s.f
	Furniture	
	2 24" x 36" x 72" metal shelving  Security	
	standard commercial lockset	

Detail Space Requirements

Police Station

4.03	Furniture Storage	100 s.f.
	General	
	<ul> <li>additional space provided for cots, blankets, etc.</li> </ul> Furniture	
	2 24" x 36" x 72" metal shelving	
	Security  • standard commercial lockset	
4.04	Kitchenette	20 s.f
	Casework and Built-ins 6 lineal feet of base cabinets 6 lineal feet of upper cabinets	
	Equipment  refrigerator coffee machine	
	Plumbing 1 sink	
	1 JII IIX	
Patro	I Facilities	
Patro 5.01		240 s.f
	l Facilities	240 s.f
	Sergeants  Furniture  4 "L" workstations with chair and visitor chair 3 three drawer file cabinets  Equipment	240 s.f
	Sergeants  Furniture  4 "L" workstations with chair and visitor chair 3 three drawer file cabinets	240 s.f

# Patrol Conference

150 s.f.

Furniture

Security

5.02

1 conference table with six chairs

standard commercial lockset

# **Equipment**

1 computer connection at table

Detail Space Requirements

# Police Station

New Programmed Area Name

Program Area

	<ul><li>1 wall telephone(s)</li><li>radio speaker with volume control</li></ul>	
	Display	
	1 4' x 6' marker board	
	Security - standard commercial lockset	
5.03	Report Preparation/Squad Room	200 s.f
J.03	General	200 3.1
	<ul> <li>locate adjacent to dispatch with window between</li> <li>locate adjacent to licensing with window</li> </ul>	
	Furniture	
	<ul><li>3 "L" computer workstations</li><li>1 conference table with eight chairs</li><li>4 two drawer lateral files</li></ul>	
	Casework and Built-ins 4 lineal feet of three four form cubbies 12 lineal feet of open counter over files 30 staff mailboxes	
	<ul><li>Equipment</li><li>1 wall telephone(s)</li><li>radio speaker with volume control</li></ul>	
	Display	
	<ul><li>1 4' x 4' marker board</li><li>1 4' x 4' tack board</li></ul>	
5.04	Quartermaster Storage	80 s.f.
	Furniture 6 24" x 36" x 72" five tier metal shelving	
	Electrical 2 wall mtd. charging rack 1 recharge for radar units	
	Security  standard commercial lockset	
	Weapons Cleaning	40 s.f
5.05	_ · ·	
5.05	Furniture  1 six foot stainless steel workbench	

**Detail Space Requirements** 

Police Station

# New Programmed Area Name

Program Area

# Weapons Cleaning - continued

- weapons clearing trap
- radio speaker with volume control

# Casework and Built-ins

6 lineal feet of base cabinet with epoxy resin countertop

#### Mechanical

exhaust for cleaning fluid

# Security

none

# 5.06 Armory

40 s.f.

# Furniture

- 6 lineal feet of long gun storage rack
- 2 24" x 36" x 72" six tier metal shelving

# 6. Investigative

### 6.01 Detective's Office x 2

280 s.f.

### Furniture

- 1 "L" workstation
- 2 two drawer lateral file cabinets
- 2 visitor chairs

# Casework and Built-ins

- 8 If open countertop (over files)
- 16 If wall shelving (over files)

# Equipment

- 1 computer (@ workstation)
- 1 printer (@ workstation)
- 1 telephone (@ workstation)

### Security

standard commercial lockset

# 6.02 Interview Room

100 s.f.

#### General

locate between detective offices

#### **Furniture**

1 fixed table w/ four chairs

#### Electrical

- 1 light switch w/ "in use" light
- 1 panic device
- laptop cable

**Detail Space Requirements** 

Police Station

New Programmed Area Name

Interview Room - continued

Acoustics

• partitions to extend to underside of structure
• sound batt insul. in stud partitions
• acoustic wall panels on one wall

# Security

- standard commercial lockset
- discreet CCTV audio and video surveillance

# Special

· one-way glass to each office

# 6.03 Equipment Storage Room

12 s.f.

#### **Furniture**

2 18" x 36" x 72" - 5 tier shelving

#### Security

standard commercial lockset

# 7. Department Administration

# **Administrative Assistant** 7.01 120 s.f. **Furniture** 1 "U" workstation with chair 3 four drawer lateral file cabinets typewriter stand **Equipment** 1 computer 1 multifunction device 1 telephone 1 typewriter Security standard commercial lockset Reprographics/Work Area 7.02 20 s.f. Casework and Built-ins 6 lineal feet of base & upper cabinets **Equipment** 1 multifunction printer 1 paper shredder mail machine

**Detail Space Requirements** 

Police Station

New Programmed Area Name Program Area **Future Office** 7.03 120 s.f. **Furniture** 1 "U" workstation 3 two drawer lateral file cabinets 2 visitor chairs Casework and Built-ins 9 If open countertop (over files) 18 If wall shelving (over files) **Equipment** 1 computer (@ workstation) 1 telephone (@ workstation) Security standard commercial lockset **Accessory Areas**  coat closet Lieutenant's Office 7.04 160 s.f. **Furniture** 1 "U" workstations 3 two drawer lateral file cabinets 1 worktable with four chairs

# Casework and Built-ins

- 9 If open countertop (over files)
- 18 If wall shelving (over files)

#### Equipment

- 1 computer (@ workstation)
- 1 telephone (@ workstation)

#### Acoustics

• sound batt insul. in stud partitions

#### Security

standard commercial lockset

# **Accessory Areas**

coat closet

# 7.05 Chief's Office

180 s.f.

#### General

provide direct access from exterior

### **Furniture**

- 1 exec. desk w/ credenza
- 2 two drawer lateral files
- 2 visitor chairs

Police Station

New	Program	med A	rea N	ame

8.

nmed Are	ea Name	Program Area
	Chief's Office - continued	
	Casework and Built-ins 6 If open countertop (over files) 12 If wall shelving (over files)	
	Equipment  1 computer (@ workstation) 1 printer (@ workstation) 1 telephone (@ workstation)	
	<ul> <li>Acoustics</li> <li>partitions to extend to underside of structure</li> <li>sound batt insul. in stud partitions</li> </ul>	
	Security - standard commercial lockset	
	<ul> <li>standard commercial lockset</li> <li>Accessory Areas</li> <li>large closet</li> </ul>	
7.06	Conference Room	320 s.f
	Furniture 1 conference table w/ 16 chairs	
	Casework and Built-ins 6 lineal feet base cabinets	
	Equipment  1 telephone 1 laptop/projection provision at table 1 flat panel monitor	
	<ul> <li>Acoustics</li> <li>partitions to extend to underside of structure</li> <li>sound batt insulation in stud partitions</li> </ul>	
	Security - standard commercial lockset	
Staff	Facilities	
8.01	Male Restroom/shower	210 s.f
	Casework and Built-ins 6 lineal feet open countertop 6 lineal feet bench	
	Plumbing 1 hc toilet stall	

2 urinals 2 sink 2 shower New Progre

# Westminster, Massachusetts Detail Space Requirements

Police Station

ned Are	ea Name	Program Area
	Male Restroom/shower - continued	
	Security  standard commercial push/pull	
3.02	Male Locker Room	400 s.f
	Equipment  24 2'x 2'-6" x 6' lockers  4 space for future lockers  1 4' wet gear rack  1 shoe shine station  1 weapons clearing trap	
	<ul><li>Security</li><li>standard commercial push/pull</li></ul>	
8.03	Female Restroom/shower	160 s.f
	Casework and Built-ins 4 lineal feet open countertop 3 lineal feet bench	
	Plumbing 1 hc toilet stall 1 sink 1 shower	
	Security - standard commercial push/pull	
3.04	Female Locker Room	110 s.f
	Equipment 6 2'x 2'-6" x 6' lockers 2 space for future lockers 1 2' wet gear rack 1 shoe shine station	
	<ul><li>Security</li><li>standard commercial push/pull</li></ul>	
3.05	Break Room	180 s.f
	Furniture 1 table(s) with four chairs	
	Casework and Built-ins 8 If base and upper cab.	
	Equipment 1 refrigerator	

1 microwave (in casework)

61

# Westminster, Massachusetts

**Detail Space Requirements** 

# Police Station

Program Area New Programmed Area Name **Break Room - continued** 1 coffee machine (provision) 1 residential oven w/ cooktop 1 dishwasher Plumbing 1 double bowl sink (in casework) Miscellaneous Male Restroom 8.06 65 s.f. Casework and Built-ins 4 lineal feet open countertop Plumbing 1 hc toilet stall 1 urinals 1 sink (in counter) Security • standard commercial lockset 8.07 Miscellaneous Female Restroom 65 s.f. Casework and Built-ins 4 lineal feet open countertop Plumbina 1 hc toilet stall 1 toilet stall 1 sink (in counter) Security • standard commercial lockset 8.08 Fitness Center 500 s.f. **Equipment**  TBD Special mirrors full height one wall Acoustics sound batt insul. in stud partitions

standard commercial lockset

Security

Police Station

	rea Name Program Are
9.01	Evidence Laboratory 150 s
	Furniture 1 3' x 6' lab tables
	Casework and Built-ins  24 lineal feet of base cabinets  12 lineal feet of upper cabinets
	Equipment 1 counter top fuming tank 1 drying cabinet 2 pass thru locker units to evidence storage
	<b>Plumbing</b> 1 double bowl sink
	Security  • proximity access control
9.02	Evidence Receiving 40 s
	Furniture 1 computer station w/printer  Casework and Built-ins 5 lineal feet of base cabinet for storage of packaging materials 1 lineal feet of 6 - tier form cubbies
	<ul> <li>Equipment</li> <li>2 pass thru locker units - two large capacity units minimum</li> <li>one from hall</li> <li>one unit from prisoner processing</li> <li>1 refrigerated pass thru (in units above)</li> </ul> Security
	proximity access control
9.03	Evidence Storage 400 s
	Furniture  4 24" x 36" x 72" metal shelving  90 lineal feet of high - density 5 - tier evidence storage system  1 valuables safe  12 lineal feet of locked longarms racks  1 3' x 2' x 6' lockable handgun storage cabinet  1 3' x 2' x 6' vented lockable drug storage cabinet
	Equipment 1 refrigerator
	Security

**Detail Space Requirements** 

# Police Station

Program Area New Programmed Area Name Evidence Storage - continued proximity access control w/ "pin" keypad cctv monitoring 80 s.f. Weapons Storage **Furniture** 12 lineal feet of long arms rack with shelving for handguns above Mechanical 100% exhaust Security proximity access control w/ "pin" keypad cctv monitoring **Bulk Found Property Room** 300 s.f. Security overhead door or gate with proximity access control proximity access control 10. **Prisoner Processing** 10.01 Sally Port (1-cruiser) 450 s.f. General 2 12' x 12' overhead doors for each bay 1 man door Plumbing 1 eye wash/emergency shower 1 floor drain per bay Security • interlock all doors for one at a time operation • cctv monitoring of interior and approach proximity access control in/out to Pris. Proc. proximity access control and remote release of OH doors from dispatch wire mesh partition to separate bay for vehicle processing **Processing Area** 250 s.f. 10.02 Casework and Built-ins booking control workstation booking bench with handcuff rings

Police Station

# New Programmed Area Name

Program Area

	Processing Area - continued
	Equipment  1 automated fingerprint machine 1 telephone (@ workstation) 1 telephone with two handsets for language line services 1 computer (@ workstation) 6 property lockers - two large enough for guitars/backpacks 1 mug shot camera on mount (@ workstation) • static gray back drop (to match registry of motor vehicles) w/ height markers  Security • proximity access control • cctv monitoring of all areas • panic devices throughout • automatic openers for doors from sallyport • use least possible number of cameras to monitor booking • prisoner release exit • weapons locker outside all entrances
10.03	Holding Cell 50 s.f.
	Casework and Built-ins 8 lineal foot bench with cuff rail
	Electrical 1 detention grade light fixtures
10.04	Security  • minimum 10' high ceilings  • detention grade sliding door hardware w/ cuff door  • audio/video surveillance  • visual observation from booking area  • tamper resistant hvac grills - 1/8" holes maximum  Intoxilyzer Area  12 s.f.
	Casework and Built-ins 6 lineal feet base cabinet w/ epoxy resin countertop 1 booking bench w/ cuff rail  Electrical 1 tel/data for intoxilyzer
10.05	Custodial Closet 20 s.f.
	<b>Plumbing</b> 1 mop sink

# Police Station

NOW	Dragra	mmed	Aron	Nama
NEW	rioala	mmeo	AIEG	name

	1 mop rack
	Security  • high security lockset
10.06	Interview Room 100 s.f
	use for bail and lawyer meetings, provide vestibule near prisone release exit
	Furniture 1 fixed table w/ two chairs
	Electrical  1 light switch w/ "in use" light 1 panic device
	Equipment 1 phone discreetly located
	<ul> <li>Acoustics</li> <li>partitions to extend to underside of structure</li> <li>Acoustic wall panels on one wall</li> </ul>
	Security  high security lockset discreet CCTV audio and video surveillance w/ local control
10.07	Detention Restroom/shower 50 s.f

#### **Detention Facilities** 11 .

11.01	Unisex Cells (x3)	400 s.f.
	Casework and Built-ins 1 32" x 72" x 18" concrete bunk	
	<ul><li>Equipment</li><li>telephone with long phone line</li></ul>	
	Plumbing 1 detention combination fixture	

on

			Police Sto
w Progra	mmed Are	a Name	Program Area
- 1		Unisex Cells - continued	
		Electrical  1 detention grade light fixtures  • audio/video surveillance  • tamper resistant hvac grills - 1/8" holes maximum	
12 .	Vehic	le Storage	
	12.01	Vehicle Processing/Cruiser Maintenance	960 s.f.
		General 2 bays 2 12' x 12' overhead door	
		Equipment 1 tool cabinet 1 6' work bench 1 12' tire rack 1 55 gallon oil storage tank 1 tire balancer 1 four post lift	
	12.02	Mechanic's Storage	40 s.f.
		Furniture 3 24" x 36" x 72" five tier shelving  Security • standard commercial lockset	
13 .	Buildiı	ng Services	
	13.01	Custodial Closets x 1	20 s.f.
		Plumbing 1 mop sink  Equipment 1 mop rack  Security • standard commercial lockset	
	13.02	Facility Maintenance Storage	80 s.f.
		Furniture 2 18" x 36" x 72"- five tier metal shelving	

• standard commercial lockset

Security

# Police Station

grammed Are	a Name	Program i	Arec
13.03	Boiler Room	200	s.f
	confirm size with system selection		
	Security		
	standard commercial lockset		
13.04	Sprinkler Room	50	s.f
	confirm size with system selection		
	Security		
	standard commercial lockset		
13.05	Air Handling Equipment Room	TBD	s.f
	Use attic or roof top		
13.06	Electrical Room	80	s.f
	confirm size with system selection		
	Security		
	standard commercial lockset		
13.07	Emergency Electrical Room	60	s.f
	confirm size with system selection		
	Security		
	<ul> <li>standard commercial lockset</li> </ul>		
	2-hour fire rated construction		
. Vertic	al Circulation		
14.01	Stair x 2 x 2-floors	800	s.f
1	assumed floor count		
14.02	Elevator x 2-floors	120	s.f
	hc sized cab		

# Westminster, Massachusetts Site Needs Assessment

New Pro	ogrammed Area Name	Quan	tity	Programmed	Area
<b>S.1</b>	Building Area				
	Building Footprint	2	story	9,704	s.f.
	Future Building Growth (25% of programmed area)			2426	s.f.
	Subtotal:			13,560	s.f.
<b>S.2</b>	Parking Area				
	Visitor Parking	11	spaces	1,815	s.f.
	Visitor Handicapped Parking	1	spaces	270	s.f.
	Staff Parking	30	spaces	4,950	s.f.
	Staff Handicapped Parking	1	spaces	270	s.f.
	Cruiser Parking	12	spaces	1,980	s.f.
	Oversize Fleet Parking	2	spaces	650	s.f.
	Travel Lane Allowance			7,900	s.f.
	Subtotal:			17,835	s.f.
<b>S.3</b>	Site Utilities				
	Electrical Transformers			100	s.f.
	Emergency Generator			250	s.f.
	Antenna Tower			500	s.f.
	AC Equipment			400	s.f.
	Dumpsters			240	s.f.
	Storm Water Retention			3,200	s.f.
	Subtotal:			4,690	s.f.
<b>S.4</b>	Site Amenities				
	Impound Lot	6	spaces	1,200	s.f.
	Subtotal:			1,200	s.f.
<b>S.5</b>	Setbacks and Green Space				
	Green space			14,900	s.f.
	Setbacks			16,000	s.f.
	Subtotal:			30,900	s.f.
	Summation				
	Minimum useable site area			68,185	s.f.
	Minimum useable site acerage			1.57	ac.



FIRE STATION PROGRAM



# Westminster, Massachusetts Space Needs Summary

Fire Facility

New Prog	grammed Are	ea Name		Program Are	a ,
1.	Public			Initial	
$\neg$	1.01	Vestibule		80	s.f.
	1.02	Lobby With Display Area		550	s.f.
	1.03	Male Restroom		160	s.f.
	1.04	Female Restroom		160	s.f.
			Subtotal:	950	s.f.
2.	Admin	istration			
	2.01	Meeting/Training/Library/Kitchenette		1400	s.f.
	2.02	Meeting Room Storage		144	s.f.
	2.03	Conference Room		200	s.f.
	2.04	Chief's Office		180	s.f.
	2.05	Captains Office		160	s.f.
	2.06	Shared Bunk		144	s.f.
	2.07	Department Administrators Office		120	s.f.
	2.08	Fire Prevention / Shared Office With EMS		300	s.f.
	2.09	Workspace		100	s.f.
	2.10	Records Storage		100	s.f.
	2.11	Network/IT		200	s.f.
	2.12	Male Restroom		60	s.f.
	2.13	Female Restroom		60	s.f.
			Subtotal:	3,168	s.f.
3.	Firefigh	nters/EMTs			
	3.01	Firefighter's/EMTs Day Room		300	s.f.
	3.02	Kitchen		250	s.f.
	3.03	Dining		200	s.f.
	3.04	Exercise		400	s.f.
	3.05	Bunkers/Bed		480	s.f.
	3.06	Baths/Showers		180	s.f.
	3.07	Lockers		250	s.f.
	3.08	Housekeeping Storage			s.f.
	3.09	Private Lobby			s.f.
			Subtotal:	2,152	s.f.

### Westminster, Massachusetts Space Needs Summary

Fire Facility

Du e		Area Name Program Ar			
rrog	rammed Ai	rea Name		Program Are	ed .
4 .	Appa	ratus/Training			
	4.01	Apparatus Bays (12) - 6 double-deep		8320	s.f.
	4.02	Training Tower (Second egress stair)		600	s.f.
			Subtotal:	8,920	s.f.
5.	Firemo	atic Support			
	5.01	Mezzanine		1280	s.f.
	5.02	Storage Room #01		100	s.f.
	5.03	Work Room		120	s.f.
	5.04	Firematic DeCon/Laundry		168	s.f.
	5.05	EMS Storage		64	s.f.
	5.06	Air Room (SCBA)		200	s.f.
	5.07	Turnout Gear		300	s.f.
	5.08	Radio/Communications Room		144	s.f.
	5.09	Unisex Restroom		60	s.f.
1			Subtotal:	2,436	s.f.
<b>3</b> .	Suppo	ort			
	6.01	Custodial Closets x 2		96	s.f.
	6.02	Mechanical Room		320	s.f.
	6.03	Sprinkler Room		TBD	s.f.
	6.04	Air Handling Equipment Room		TBD	s.f.
	6.05 6.06	Electrical Room		TBD TBD	s.f.
+	0.00	Emergency Electrical Room	Subtotal:	416	
1			SUDIOIGI.	410	3.I.
7 .	Vertic	le Circulation			
	7.01	Stair x 2 x 2-floors		400	s.f.
	7.02	Elevator x 2-floors		120	s.f.
	7.03	Elevator Machine Room		60	s.f.
T			Subtotal:	580	s.f.
	Summ	nation			
		Facility net area:		18,622	s.f.
		Net to gross adjustment (20%)		3,724	s.f.
_					

Public			
1.01	Vestibule	80	s.f.
	Security		
1.02	Lobby With Display Area	550	s.f.
	General     lobby design should reflect an environment of service to community and visitors	o the	
	Security		
	Equipment  1 public access computer terminals		
	Casework and built-ins  pamphlet/form rack for community information display cases		
	Display Display for antique pumper - 100 s.f.  I flat panel information monitor display cases for historic artifacts Plaque & Artwork graphic Town map for visitor assistance		
	Mechanical  odo not recirculate air into staff areas		
	Plumbing 1 drinking fountain (accessible)		
1.03	Male Restroom	160	s.f
1.03	Male Restroom  Plumbing    water closet   urinal   sink   floor drain with trap primer	160	s.f

**Detail Space Requirements** 

Fire Station

#### New Programmed Area Name

Program Area

#### Male Restroom - continued

#### **Equipment**

- toilet accessories as required
- mirrors at sinks
- changing station

#### Security

- ballistic protection in walls interfacing staff areas
- avoid concealed areas within room or above ceiling

#### 1.04 Female Restroom

160 s.f.

#### Plumbing

- 2 water closet
- 1 sink
- 1 floor drain with trap primer

#### Equipment

- toilet accessories as required
- mirrors at sinks
- changing station

#### Security

- ballistic protection in walls interfacing staff areas
- avoid concealed areas within room or above ceiling

#### 2. Administration

#### 2.01 Meeting/Training/Library/Kitchenette

1,400 s.f.

#### **Description**

- Seating for 75 at tables and chairs
- AV, TV, Screen, Lectern, etc.: Yes, all and Smart board, (2) ceiling projectors, Wi-Fi.
- Kitchenette equipment: small refrigerator, counter, sink, coffee with water line, base
- Computer/communications: Multi-purpose, secondary E.O.C. podium-based media
- Library: Seating for 3-4 at computer study carousels, book and computer supplies
- Adjacencies/comments: Black out shades, sound system, 50/50 split room divider,

chair rail all around.

iica Aic	a Name Program	А
2.02	Meeting Room Storage 144	! !
	Use: Store tables and chairs on racks	
	Adjacencies/comments: Chair rail all round, wall cabinets or one wall, double doors,	n
2.03	Conference Room 200	) ;
	<ul> <li>Description</li> <li>Seating for 8-10</li> <li>AV, TV, Screen, Lectern, etc.: All and whiteboard</li> <li>Computer/communications: Yes, Wi-Fi and cable, ceiling projector.</li> </ul>	
2.04	Chief's Office 180	)
	Chief's Office  Furnishings  Desk, credenza, files, table for 6, bookshelves, 4 plex at desk.  Comments/Adjacencies  Secure, TV and presenting room off office  Adjacent to shared bunk	•
2.05	Captains Office 160	)
	Description Captain's Office Furnishings Desk, credenza, files, table for 6, bookshelves, 4 plex at desk Comments/Adjacencies Adjacent to shared bunk	
2.06	Shared Bunk 144	ļ
	Description Shared bunk for Chief & Captain Furnishings	
	2 Beds 2 Wardrobes Comments/Adjacencies	

mod 7 ii	ea Name Pro	ogram .	Are
2.07	Department Administrators Office	120	s.
2.08	Description Department Administrator's Office Furnishings Desk, cabinets, copier, printer, file cabinet. Comments/Adjacencies Chief and Captain's offices need to be adjacent to fro entry. Fire Prevention / Shared Office With EMS	nt <b>300</b>	s.
	Description Fire Prevention, Shared Office Seating for 2 Furnishings 3 desks, storage drawers with flat surface for Plan review Comments/Adjacencies Office needs to be adjacent to entry, Public access Secure		
2.09	Workspace	100	S
	Description  Base and wall cabinets, solid surface counter, mailing  Comments/Adjacencies  Widened corridor to house copier, large format printer/plotter, office supplies.		
2.10	Records Storage	100	s
	Description File cabinets, lateral files, table and chairs Fire Rating 2 hours Comments/Adjacencies Secure		

Fire Station

New Programmed Area Name

Program Area

	Network/IT - continued
	HVAC  Dedicated split system, fully alarmed for heat, humidity, static electricity.  Comments/Adjacencies  Secure  Work space with 10 lineal feet of counter top with storage  Adjacencies/comments: Manual sprinkler, combined with Communication System.  Racks grounded, static dissipation floor tile, 1 UPS for all racks.
2.12	Male Restroom 60 s.1
	Plumbing    water closet   sink   floor drain with trap primer  Equipment  • toilet accessories as required • mirrors at sinks
2.13	Female Restroom 60 s.:
	Plumbing  1 water closet 1 sink 1 floor drain with trap primer
	<ul> <li>Equipment</li> <li>toilet accessories as required</li> <li>mirrors at sinks</li> <li>changing station</li> </ul>
Firefi	ghter's/EMTs
3.01	Firefighter's/EMTs Day Room 300 s.
	<ul> <li>Description</li> <li>Recliners and TV</li> <li>Number of Seats/Type: 4 - 6</li> <li>Furnishings</li> <li>TV, end tables.</li> </ul>

Detail Space Requirements

Fire Station

#### New Programmed Area Name

Program Area

#### Firefighter's/EMTs Day Room - continued

#### Comments/Adjacencies

Kitchen and bunk suite, clear path to Bays, easily cleaned, no carpet, no fabric on seating; utilized by Mutual Aid.

3.02 Kitchen 250 s.f.

#### **Description**

Full Commercial equipment and appliances.

#### **Equipment**

Ansul hood, stove, stainless steel, 3 – sinks, 1 for food prep, all potential with garbage disposal, 1 hand washing sink, microwave, under counter dish washer, ice machine.

Refrigerators: 2 with freezers attached.

Pantry/Food Storage: 4 locked stainless steel shelves; one for each shift

#### Finishes/Materials

All tile floor and walls, moisture resistant ceiling, Quartz or stainless steel countertops, high-density cabinets.

#### Comments/Adjacencies

Floor drains, 1/4" piping for water to refrigerator and coffee maker, 2'-6" deep counters, comfort height, exterior door to patio.

3.03 Dining 200 s.f.

#### Description

Open to kitchen

#### Equipment

Table for 12, TV mounted on wall.

#### Comments/Adjacencies

Kitchen, Day Room and Bays.

3.04 Exercise 400 s.f.

#### **Equipment**

- Weights: Yes,
- Cardio: Treadmill and Elliptical
- Universal: Yes
- Other: TV, blocking in walls, mirrors on one wall, hand rail.

#### Comments/Adjacencies

Recycled rubber floor, window to corridor, intercom, high TV mount, high ceiling, dedicated HVAC (good ventilation).

3.05	Bunkers/Bed	480	s.f
	Bunk Type  • (4) singles - can be converted to doubles in future  • Separate suites, quiet and private  Furnishings  Bed, wardrobes for 4, small desk  Comments/Adjacencies  Overhead fan, individual climate controls, lighting come with alarms, tones in bunk. No Zetron system, NFPA 1581 3 "Sleeping Areas", direct access to Bays.		
3.06	Baths/Showers	180	s.f
	Description Individual, 2 are required, unisex, sink, shower, water clos Location Within bunk suite Comments/Adjacencies All tile floors and walls, floor drain, solid surface countertelever type handles for sink.		
3.07	Lockers	250	s.f
	Description Separate rooms for call responders. Location Bunker suite Lockers 40 male, 15 Female: 12" wide full height, sloped top. Comments/Adjacencies Male and female to share room, tile floor and all exposed walls, phenolic benches.	d	
3.08	Housekeeping Storage	44	s.f
	Description Washer, dryer, folding table. Comments/Adjacencies Shelving, mop and broom holder, dry goods, cleaning su	ilqqı	es.

Detail Space Requirements

on

med Ar	ea Name	Program
3.09	Private Lobby	48
	Description	
	Access directly to Administration	
Appa	Iratus/Training	
4.01	Apparatus Bays (12) - 6 double-deep	8,320
	Vehicles - total of 9	
	<ul> <li>E1 Type: Pump Length: 34' Weight: 47,000 Capacity:</li> </ul>	1
	<ul> <li>E1 Type: Full Length: 34 Weight: 47,000 Capacity:</li> <li>E2 Type: Pump Length: 40' Weight: 62,000 Capacity:</li> </ul>	
	<ul> <li>E3 Type: Pump Length: 32' Weight: 53,000 Capacity:</li> </ul>	
	<ul> <li>It Type: Ladder Length: 42' Weight: 81,000 Capacity.</li> </ul>	
	Al Type: Ambulance Length: 22' Weight: 15,000 Cap	
	A2 Type: Ambulance Length: 22' Weight: 15,000 Cap	
	Car 3 Type: Truck Length: 18' Weight: 8,000 Capacity	
	Boat Type: Nautic Length: 10'	y · ∠
	UTV Type: Gravely Length: 8	
	Type of Bays	
	Drive-thru - respond in both directions	
	All double deep, back to back	
	Overhead Doors	
	2 rows of glass.	
	Front: Number: 6 Width: 14 Height: 14	
	Rear: Number: 6 Width: 14 Height: 14	
	Foam	
	Type: 20-30 gallons/5 gallon pails.	
	Trench Drains	
	centered under all apparatus – to Oil/Water separa	tor.
	Hose Reals	
	Hannay wall mounted with 50' x 3/4" hose, 6 total; 3	front ar
	rear. One each front and rear with hot and cold we	
	Fume Exhaust	3101.
	Plymovent – hydraulic, all Bays, 2 fans; one for each	group c
	apparatus.	
	Truck Fills	
	Overhead: One, center location.	
	Outdoor hydrant: Yes Location: Adjacent to Apron.	
	Overhead Fans	
	BAF or eq.	
	Electrical Drops	
	II Bays – 20 AMP/Drop.	
	Air Drops (2) In-Line Air Dryer, no combination plugs.	

**Detail Space Requirements** 

Fire Station

New Programmed Area Name

Program Area

#### Apparatus Bays (12) - 6 double-deep - continued

#### **Compressed Air**

2 in front and 2 in rear on overhead reels.

#### Sinks

deep bowl.

#### **Finishes**

Epoxy flooring, non-slip, multi-color with BackOin safety stripe

#### Ice Machine

For ambulances

#### **Comments/Adjacencies**

Introduce daylighting, hand towel dispenser at each overhead door pilaster.

#### 4.02 Training Tower (Second egress stair)

600 s.f.

#### **Description**

Design as integral part of Bays and Connected to Mezzanine.

#### **Features**

- Rappelling: Yes
- Stairs: Yes
- Roof Access: Yes, reinforce parapet and roof surface at training locations.
- Roof training: Yes
- Windows: Yes, several levels and sizes.
  - a. Need a window at first floor level.

Need window at the height of a 2-story residential building for the

- b. following evolutions: Window entry.
- Hose: Yes
- Confined Space: Yes
- Sprinkler: Yes Dry: Yes
  - a. Use water service as training prop.
- Blackout: Yes
- Hose Drying: Yes Winch: Yes, 2 Ton.
- Other Specialized Training: Modular setup, overhead grid, rappelling points and tie-off, look at materials for walls and bail out points.

		Fire	_	
mmed Are	a Name Pro	ogram <i>i</i>	Arec	
Firemo	atic Support			
5.01	Mezzanine	1280	s.f.	
	Description  Large as possible, attached to tower, share stairs.  Size  Full depth of Bays, training, possible storage, no mechan	nical (	Jse:	
5.02	Storage Room #01	100	s.f	
	Description  Hose, fittings and nozzles  Location  Off the bays  Comments/Adjacencies  Racks, shelves and wall cabinets			
5.03	Work Room	120	s.f	
	<ul> <li>Equipment</li> <li>Mechanic: Town does large repairs outside of Station.</li> <li>Service: Pump service</li> <li>Workbench: Yes</li> <li>Tool storage: Yes, hand tools</li> <li>Power tools: Grinder, drill press</li> <li>Air: Yes, for tools.</li> <li>Water: Yes, deep bowl, stainless steel sink.</li> </ul> Comments/Adjacencies Fire department needs stainless steel wall cabinets and shelves.			
5.04	Firematic DeCon/Laundry	168	s.f	
	<ul> <li>Sink: Yes, stainless steel with sideboard.</li> <li>Extractor: Will need to purchase. Brand: TBA</li> <li>Gear dryer: Will need to purchase Dehydrator type.</li> <li>Clothes washer: Yes, located on clean side of Station.</li> <li>Clothes Dryer: Yes located on clean side of Station.</li> <li>Drench/Eye Wash: Yes, cartridge type, proximity to work</li> <li>Red Bag and Sharps: Yes</li> <li>Holding Tank: No, clean at scene or hospital.</li> <li>Backboard cleaning: On occasion.</li> </ul>	(roon	Դ.	

Fire Station

New Programmed Area Name

Program Area

#### Firematic DeCon/Laundry - continued

- Drench Shower: Yes
- Blood borne pathogens: Minimal, clean at hospital.

#### Comments/Adjacencies

DeCon done at hospital, NFPA 1581. Direct access to Hot Zone and transition area, exterior door, floor drains, hose bib, concrete pad for extractor.

#### 5.05 EMS Storage

64 s.f.

#### Description

Restock ambulance, EMS supplies (blankets, bandages, etc.).

#### Security

- Access control
- camera monitored

#### Comments/Adjacencies

Stainless steel shelving all around room. Locked cabinet for meds, duplex outlet for future refrigerator. Locate Adjacent to Ambulance Bays.

#### 5.06 Air Room (SCBA)

200 s.f.

#### **Equipment**

Sink: Yes, 4 compartment, stainless steel, NFPA 1581 Counters: 2 sideboards, mask hooks above sink Air compressor: Yes, 3 bottles, 4,500 and 5,500 lbs.

7.4.1 Remote fill station: Yes, from compressor to Air Room SCBA storage: All bottles Rack: 4 on a rack.

Repair: small, masks.

#### O2 Storage

Number of Cylinders: 16 - D and 1 - M. Look at system to hold oxygen tanks (not chains on wall).

#### Comments/Adjacencies

Compressor in separate room. Will need air supply, sound protection and room exhaust.

Detail Space Requirements

Fire Station

5.07	Turnout Gear	ogram Are
<u> </u>	Description 40 required, largest locker possible, secured to walls.  Equipment Racks: Gear Grid or Ready Rack.  Comments/Adjacencies Over Head fans, HVAC and constant exhaust, HEPA Filter mounted, benches, LED lighting, floor drains, 4 – plex or around room at top of lockers	er, wall
5.08	Radio/Communications Room	144 s.
	Watchroom - Adjacent to Bays with direct vision  Seating requirements 3  Door operation Control of all 12 doors, numbered  Equipment Traffic control: No, Opticom on trucks, depends on loc Station. Internal paging system: Yes, and base radio. Siren: Yes, part of ISO Rating. Computer equipment: Yes, for each station Closed Circuit TV, Phones, Weather Station: Yes File cabinets: Yes Wall mounted items: Maps Rechargeable items (plectrons): Portable radio batterie 911 tie in: No Console: - Phones, switches, door controls, siren. Lockable storage: No	
	Comments/Adjacencies Secondary Communication Center for Dispatch, adherenced HIPPA requirements for report writing.	re to
	Unisex Restroom	60 s.

All hard washable surfaces, moisture resistant ceiling.

Supp	ort		
6.01	Custodial Closets x 2	96	s.
	<b>Plumbing</b> 1 mop sink		
	Equipment 1 mop rack		
	Security - standard commercial lockset		
6.02	Mechanical Room	320	s.
	confirm size with system selection		
	Security - standard commercial lockset		
6.03	Sprinkler Room	TBD	s.
	confirm size with system selection		
	Security - standard commercial lockset		
6.04	Air Handling Equipment Room	TBD	s.
	Use attic or roof top		
6.05	Electrical Room	TBD	s.
	confirm size with system selection		
	Security - standard commercial lockset		
6.06	Emergency Electrical Room	TBD	s.
	confirm size with system selection		
	Security     standard commercial lockset     2-hour fire rated construction		

Vert	ical Circulation		
7.01	Stair x 2 x 2-floors	400	s.f
	<ul><li>Training tower will be utilized for one of the stairs</li><li>assumed floor count</li></ul>		
7.02	Elevator x 2-floors	120	s.f
	hc sized cab		
7.03	Elevator Machine Room	60	s.f

# Westminster, Massachusetts Site Needs Assessment

Fire Facility

New Pr	ogrammed Area Name	Quan	tity	Programmed	l Area
<b>S.1</b>	Building Area				
	Building Footprint	2	story	13,966	s.f.
	Future Building Growth (25% of programmed area)			3492	s.f.
	Subtotal:			17,458	s.f.
<b>S.2</b>	Parking Area				
	Visitor Parking	4	spaces	660	s.f.
	Visitor Handicapped Parking	1	spaces	270	s.f.
	Staff On call Parking	30	spaces	4,950	s.f.
	Staff Handicapped Parking	1	spaces	270	s.f.
	Staff Parking	4	spaces	660	s.f.
	Travel Lane Allowance			10,000	s.f.
	Subtotal:			16,810	s.f.
<b>S.3</b>	Site Utilities				
	Electrical Transformers			100	s.f.
	Emergency Generator			300	s.f.
	Antenna Tower			500	s.f.
	AC Equipment			400	s.f.
	Dumpsters			240	s.f.
	Storm Water Retention			3,500	s.f.
	Subtotal:			5,040	s.f.
<b>S.4</b>	Site Amenities				
	Patio / Grill area			1,200	s.f.
	Training Props	6	spaces	1,200	s.f.
	Subtotal:			2,400	s.f.
<b>S.5</b>	Setbacks and Green Space				
	Green space			12,700	s.f.
	Setbacks			15,100	s.f.
	Subtotal:			27,800	s.f.
	Summation				
	Minimum useable site area			60,779	s.f.
	Minimum useable site acerage			1.4	ac.

## COMBINED PUBLIC SAFETY PROGRAM



Space Needs Summary

v Prog	rammed Area Name		Program Are	a
1.	Shared Facilities			
-1	1.01 Vestibule		80	s.f.
	1.02 Lobby With Display Area		550	
	1.03 Male Restroom		160	
	1.04 Female Restroom		160	
-1	1.05 Training Room		1400	
-1	1.06 Kitchenette/Coffee		20	s.f.
	1.07 Supply Storage		25	s.f.
-1	1.08 Furniture Storage		100	s.f.
-1	1.09 Fitness Center		500	
_				
-1	Police Facilities	Subtotal:	2995	s.f.
7	1 Office 1 definites			
2 .	Public			
	2.01 Public Interview/Licensing Room		160	s.f.
1		Subtotal:	160	s.f.
3 .	Dispatch			
+	2.004.0.1			
	3.01 Dispatch Center		450	s.f.
	3.02 Dispatch Supervisors Office		120	
	3.03 Unisex Restroom			s.f.
	3.04 Communications Equipment Room/IT		200	
	3.05 Break Area		135	
			. 33	-•••
		Subtotal:	970	. г

# **Westminster, Massachusetts**Space Needs Summary

				1 UDIIC SUIE
ew Prog	rammed A	rea Name		Program Area
4 .	Recor	rds		
	4.01	Records Archive		120 s.f.
	4.02 4.03	Central Photocopy		50 s.f. 10 s.f.
	4.03	Office Supply Storage		10 5.1.
			Subtotal:	180 s.f.
5.	Patrol	Facilities		
	F 01			0.40 - 1
	5.01 5.02	Sergeants Patrol Conference		240 s.f. 150 s.f.
	5.03	Report Preparation/Squad Room		200 s.f.
	5.04	Quartermaster Storage		80 s.f.
	5.05	Weapons Cleaning		40 s.f.
	5.06	Armory		40 s.f.
_			Subtotal:	750 - 1
			Subtotal:	750 s.f.
6.	Invest	igative		
	6.01	Detective's Office x 2		280 s.f.
	6.02	Interview Room		100 s.f.
	6.03	Equipment Storage Room		12 s.f.
-			Subtotal:	392 s.f.
7.	Deng	rtment Administration		
<del>'</del> '	Бера	mieni Adminishdion		
	7.01	Administrative Assistant		120 s.f.
	7.02	Reprographics/Work Area		20 s.f.
	7.03	Future Office		120 s.f.
	7.04	Lieutenant's Office		160 s.f.
	7.05	Chief's Office		180 s.f.
	7.06	Conference Room		320 s.f.
	00			320 3.11
			Subtotal:	920 s.f.

# PUBLIC SAFETY PROGRA

## Westminster, Massachusetts

Space Needs Summary

New Prog	rammed Area Name		Program Area
8.	Staff Facilities		
	<ul> <li>8.01 Male Restroom/shower</li> <li>8.02 Male Locker Room</li> <li>8.03 Female Restroom/shower</li> <li>8.04 Female Locker Room</li> <li>8.05 Break Room</li> <li>8.06 Miscellaneous Male Restrooms</li> <li>8.07 Miscellaneous Female Restroom</li> </ul>		210 s.f. 400 s.f. 160 s.f. 110 s.f. 180 s.f. 65 s.f. 65 s.f.
$\overline{}$		Subtotal:	1190 s.f.
9.	Property and Evidence		
	<ul><li>9.01 Evidence Laboratory</li><li>9.02 Evidence Receiving</li><li>9.03 Evidence Storage</li></ul>		150 s.f. 40 s.f. 400 s.f.
$\neg$		Subtotal:	590 s.f.
10 .	Prisoner Processing		
	<ul> <li>10.01 Sally Port (1-cruiser)</li> <li>10.02 Processing Area</li> <li>10.03 Holding Cell</li> <li>10.04 Intoxilyzer Area</li> <li>10.05 Custodial Closet</li> <li>10.06 Interview Room</li> <li>10.07 Detention Restroom/shower</li> </ul>		450 s.f. 250 s.f. 50 s.f. 12 s.f. 20 s.f. 100 s.f. 50 s.f.
		Subtotal:	932 s.f.
11 .	Detention Facilities		
	11.01 Unisex Cells (x3)		400 s.f.
$\neg$		Subtotal:	400 s.f.

# **Westminster, Massachusetts**Space Needs Summary

				FUDIIC	Ju
w Progr	ammed Are	ea Name		Program Are	ea
12 .	Vehicle	e Storage			
$\neg$		•			
- 1	12.01	Vehicle Processing/Cruiser Maintenance		960	
- 1	12.02	Mechanic's Storage		40	s.f
$\dashv$			Subtotal:	1,000	s.f
- 1	Fire Fa	cilities			
3.	Admin	istration			
- 1	13.01	Conference Room		200	
- 1	13.02	Chief's Office		180	
- 1	13.03	Captains Office		160	
- 1	13.04	Shared Bunk		144	
- 1	13.05	Department Administrators Office		120	s.f
- 1	13.06	Fire Prevention / Shared Office With EMS		300	s.f
- 1	13.07	Workspace		100	s.f
- 1	13.08	Records Storage		100	s.f
-1	13.09	Network/IT		200	s.f
			Subtotal:	1,504	s.f
4 .	Firefigh	nter's / EMTs			
	1401	Fire Field And /FAATa David David		300	c t
- 1	14.01 14.02	Firefighter's/EMTs Day Room		250	
- 1		Kitchen			
- 1	14.03	Dining		200	
- 1	14.04	Bunkers/Bed		480	
- 1	14.05	Baths/Showers		180	
- 1	14.06	Lockers		250	
- 1	14.07	Housekeeping Storage			s.f
-1	14.08	Private Lobby		48	s.t
			Subtotal:	1,752	s.f
5.	Appar	atus/Training			
T	15.01	Apparatus Bays (12) - 6 double-deep		8320	s.f
	15.02	Training Tower (Possible to be third stair)		600	
			Subtotal:	8,920	

## Westminster, Massachusetts Space Needs Summary

ew Prog	grammed Area Name		Program Are	ea
16 .	Firematic Support			
	16,01 Mezzanine		1280	s.f.
	16.02 Storage Room #01			s.f.
	16.03 Work Room		120	s.f.
	16.04 Firematic DeCon/Laundry		168	s.f.
	16.05 EMS Storage		64	s.f.
	16.06 Air Room (SCBA)		200	s.f.
	16.07 Turnout Gear		300	s.f.
	16.08 Radio/Communications Room		144	s.f.
	16.09 Unisex Restroom		60	s.f.
$\exists$		Subtotal:	2,436	s.f.
17 .	Support			
	17.01 Custodial Closets x 2		96	s.f.
	17.02 Mechanical Room		320	
	17.03 Sprinkler Room		TBD	
	17.04 Air Handling Equipment Room		TBD	s.f.
	17.05 Electrical Room		TBD	s.f.
	17.06 Emergency Electrical Room		TBD	s.f.
$\dashv$		Subtotal:	416	s.f.
18 .	Verticle Circulation			
	18.01 Stair x 3 x 2-floors		1200	c f
	18.02 Elevator x 2-floors			s.f.
	18.03 Elevator Machine Room			s.f.
$\dashv$		Subtotal:	1380	s.f.
	Summation			
	Facility net area:		26,887	ς f
	Net to gross adjustment (20%)		5,377	5.1.

	Public	Sc
	Area Name Program A	rec
Sho	ared Facilities	
1.0	1 Vestibule 80	s.f
	·	
	Samula profesion in any manufacting standards	
	fire alarm annunciator panel	
1.0	2 Lobby With Display Area 550	s.f
	lobby design should reflect an environment of service to the	
	Security	
	·	
	_	
	Furniture	
	Equipment	
	1 public access computer terminals	
	Casework and built-ins	
	1 pamphlet/form rack for community information	
	2 display cases	
	drops for cell phone donations, prescription drugs, used needl	е
	Display	
	<ul> <li>display area for antique pumper - 100 s.f.</li> </ul>	
	1 flat panel information monitor	
	2 display cases for historic artifacts	
	wall space for display of historic artifacts	

• graphic Town map for visitor assistance

Public Safety

New Programmed Area Name

Program Area

Lobby - continued	
do not recirculate air into staff areas	
Plumbing	
I drinking fountain (accessible)	
Male Restroom	160 s.f.
Plumbing	
i ·	
1 sink	
1 floor drain with trap primer	
Equipment	
toilet accessories as required	
mirrors at sinks	
changing station	
Security	
ballistic protection in walls interfacing staff areas	
avoid concealed areas within room or above ceiling	
Female Restroom	160 s.f
Dispating	
-	
1 floor drain with trap primer	
Equipment	
toilet accessories as required	
mirrors at sinks	
changing station	
Security	
ballistic protection in walls interfacing staff areas	
avoid concealed areas within room or above ceiling	
	do not recirculate air into staff areas  Plumbing     drinking fountain (accessible)  Male Restroom  Plumbing     water closet     urinal     sink     floor drain with trap primer  Equipment     toilet accessories as required     mirrors at sinks     changing station  Security     ballistic protection in walls interfacing staff areas     avoid concealed areas within room or above ceiling  Female Restroom  Plumbing     water closet     sink     floor drain with trap primer  Equipment     toilet accessories as required     mirrors at sinks     changing station  Security  Security

**Detail Space Requirements** 

Public Safety

New Programmed Area Name	New	Programr	ned Ared	a Name
--------------------------	-----	----------	----------	--------

Program Area

## 1.05 Training Room 1400 s.f.

#### Occupants

50

#### General

may be used as emergency operations center

#### Acoustics

- partitions to extend to underside of structure
- sound batt insulation in stud partitions

#### **Furniture**

- 25 2'x6' tables with chairs
- 1 "smart" podium
- center aisle and two side aisles

#### Casework and Built-ins

12 lineal feet base cabinets

#### **Equipment**

- tel/data floor boxes for tables
- 1 wall telephone
- lighting control panel
- Internal and external jacks for cable access television
- telephone line drops from ceiling

#### Display

- 2 4' x 6' marker board
- 2 flat panel monitors
- 4 4'x4' tack boards

#### Security

- proximity access control
- interlock to switch control point
- ballistic protection in walls interfacing staff areas

med Ar	ea Name	Program	Are
1.06	Kitchenette/Coffee	20	s.f
	Casework and Built-ins		
	6 lineal feet base and upper cabinets		
	Equipment		
	1 refrigerator		
	1 microwave		
	1 coffee machine (provision)		
	Plumbing		
	1 double bowl sink		
1.07	Supply Storage	25	s.
1.08	<ul> <li>2 24" x 36" x 72" metal shelving</li> <li>Security         <ul> <li>standard commercial lockset</li> </ul> </li> <li>Furniture Storage</li> </ul>	100	s.
	<ul> <li>General</li> <li>additional space provided for cots, blankets, etc.</li> </ul>		
	Furniture		
	2 24" x 36" x 72" metal shelving		
	Security		
	Security  • standard commercial lockset		

Fitness Center - continued	Program Area
Special	
mirrors full height one wall	
Acoustics	
sound batt insul. in stud partitions	
Security	
standard commercial lockset	
ce Facility	
lic	
	160 s.f.
Acoustics	
· ·	
6 linedi 1001 licensing courtier with cabinets below	
Security	
proximity access control	
•	ing probate chile
panic device	
Furniture	
1 table w/ six chairs	
Equipment	
Lyophien	
1 computer on licensing counter 1 fingerprint station	
	Acoustics

# COMBINE

#### Westminster, Massachusetts

**Detail Space Requirements** 

**Public Safety** 

New Programmed Area Name

Program Area

#### 3. Dispatch

#### 3.01 Dispatch Center

450 s.f.

#### Description

• Dispatchers serve as the public reception point.

#### **Acoustics**

- partitions to extend to underside of structure
- sound batt insul. in stud partitions
- acoustic wall panels on 20% of surface

#### **Furniture**

- 2 dispatch consoles with chairs
- 6 rolling two drawer lateral file cabinets (under counter)

#### Casework and Built-ins

- 10 I.f. open countertop
- 6 I.f. wall shelving over files (over counter)
- 4 I.f. upper cabinets (over counter)
- storage for "bug-out" bins

#### Equipment

- 1 multifunction device (on casework)
- 1 logging recorder
- 1 scanner (on casework)
- 1 leaps computer terminal at counter
- central vacuum system
- note: equipment per console as indicated below:

#### Console #1

- 2 911 monitor(s)
- 1 radio monitor
- 1 CJIS monitor
- 1 security monitor
- 1 TDD, text to 911, reverse 911
- 1 radio PD, FD and DPW
- 1 intercom
- 1 telephone

Detail Space Requirements

Public Safety

#### New Programmed Area Name

Program Area

#### **Dispatch Center - continued**

#### Console #2

- 2 911 monitor(s)
- 1 radio monitor
- 1 CJIS monitor
- 1 security monitor
- 1 TDD, text to 911, reverse 911
- 1 radio PD, FD and DPW
- 1 intercom
- 1 telephone

#### Display

- 1 GPS vehicle location monitor
- 2 large flat screen perimeter/cell security monitors
- 1 flat screen television monitor
- 1 4'x6' marker board
- 1 4' x 6' tack board

#### **Special Design Considerations**

raised access floor or directly over communications equipment

#### Mechanical

dedicated hvac system

#### **Electrical**

- all systems on UPS and emergency generator
- indirect lighting with multilevel control
- proximity access control
- ballistic protection in walls interfacing public areas
- 2-hour fire separation
- ballistic window to lobby w/ natural voice transmission
- ballistic deal tray to lobby
- ballistic package passer

#### 3.02 Dispatch Supervisors Office

120 s.f.

#### **Furniture**

- 1 Small Dispatch console
- 3 two drawer lateral file cabinets
- 1 worktable with four chairs

#### Casework and Built-ins

- 9 If open countertop (over files)
- 18 If wall shelving (over files)

**Detail Space Requirements** 

#### **Public Safety**

New Programmed Area Name

Program Area

## Dispatch Supervisors Office - continued **Equipment** 1 computer (@ workstation) telephone (@ workstation) **Acoustics** sound batt insul. in stud partitions Security standard commercial lockset **Accessory Areas** coat closet **Equipment** 1 wall telephone radio speaker **Unisex Restroom** 3.03 65 s.f. **Plumbing** 1 Water closet Sink **Equipment** 1 wall telephone 1 radio speaker **Communications Equipment Room/IT** 200 s.f. 3.04 Casework and Built-ins 10 lineal feet of open counter **Equipment** 1 electronic radio equipment racks 1 network racks 1 security rack 1 911 racks 1 future rack 1 administrative computer 16 lineal feet of 8' high plywood backboard telephone

**Detail Space Requirements** 

Public Safety

#### New Programmed Area Name

Program Area

#### Communications Equipment Room/IT - continued

- 1 logging recorder
- cable tray over racks

#### **Electrical**

- all systems on UPS and emergency generator
- 4 4" conduits from pole to communications equipment
- 4 4" conduit to antenna/microwave
- 2 future conduit to roof

#### Fire Protection

• pre-action fire suppression system

#### Security

- access from outside of dispatch
- proximity access control
- masonry wall construction or wire mesh in partitions
- 2 hour fire rating

#### 3.05 Break Area

135 s.f.

#### **Furniture**

dining counter with two chairs

#### Casework and Built-ins

8 lineal feet of base and upper cabinets

#### **Equipment**

- 1 refrigerator
- 1 microwave
- 1 coffee machine
- 12 12" x 24" x 72" dispatcher lockers

#### **Plumbing**

1 kitchen sink

#### Display

1 flat panel wall monitor with cable tv

Recor	ds		
4.01	Records Archive	120	s.f
	Furniture 72 lineal feet of high-density 5 high file storage 4 three drawer lateral file cabinets		
	Equipment 1 wall telephone		
	Security  • proximity access control  Central Photocopy	50	s.f.
4.02			
4.03	Casework and Built-ins  6 If base cabinets w/ countertop  Equipment  1 multipurpose machine 1 wall telephone(s)  Security  • none  Office Supply Storage	10	s.f
	Casework and Built-ins 30 lineal feet of shelving on standards		
Patrol	Facilities		
5.01	Sergeants	240	

**Detail Space Requirements** 

Public Safety

#### New Programmed Area Name

Program Area

#### Sergeants - continued

#### **Equipment**

- 4 computer(s)
- 4 telephone(s)
- 1 multifunction print device

#### Display

- 1 4' x 4' marker board
- 1 4' x 4' tack board
- 1 GPS vehicle tracking monitor

#### Security

standard commercial lockset

#### 5.02 Patrol Conference

150 s.f.

#### **Furniture**

1 conference table with six chairs

#### **Equipment**

- 1 computer connection at table
- 1 wall telephone(s)
- radio speaker with volume control

#### Display

1 4' x 6' marker board

#### Security

standard commercial lockset

#### 5.03 Report Preparation/Squad Room

200 s.f.

#### General

- locate adjacent to dispatch with window between
- locate adjacent to licensing with window

#### **Furniture**

- 3 "L" computer workstations
- 1 conference table with eight chairs
- 4 two drawer lateral files

New Programmed Area Name	Program Area

	Report Preparation/Squad Room - continued		
	Casework and Built-ins  4 lineal feet of three four form cubbies  12 lineal feet of open counter over files  30 staff mailboxes		
	<ul><li>Equipment</li><li>1 wall telephone(s)</li><li>radio speaker with volume control</li></ul>		
	Display 1 4' x 4' marker board 1 4' x 4' tack board		
5.04	Quartermaster Storage	80	s.f.
	Furniture 6 24" x 36" x 72" five tier metal shelving		
	Electrical  2 wall mtd. charging rack  1 recharge for radar units		
	Security  • standard commercial lockset		
5.05	Weapons Cleaning	40	s.f.
	Furniture  1 six foot stainless steel workbench		
	<ul> <li>Equipment</li> <li>ultrasonic cleaner</li> <li>weapons clearing trap</li> <li>radio speaker with volume control</li> </ul>		
	Casework and Built-ins 6 lineal feet of base cabinet with epoxy resin countertop		

med Ar	ea Name	Program	Arec
	Weapons Cleaning - continued  Mechanical		
	exhaust for cleaning fluid		
	Security		
	• none		
5.06	Armory	40	s.f
	Furniture		
	6 lineal feet of long gun storage rack		
	2 24" x 36" x 72" six tier metal shelving		
Inves	stigative		
6.01	Detective's Office x 2	280	s.f
	Furniture		
	1 "L" workstation		
	2 two drawer lateral file cabinets		
	2 visitor chairs		
	Casework and Built-ins		
	8 If open countertop (over files)		
	16 If wall shelving (over files)		
	Equipment		
	1 computer (@ workstation)		
	1 printer (@ workstation)		
	1 telephone (@ workstation)		
	Security		
	standard commercial lockset		
6.02	Interview Room	100	s.f
	Comment		
	<ul><li>General</li><li>locate between detective offices</li></ul>		
	Furniture  1 fixed table w/ four chairs		

**Detail Space Requirements** 

Public Safety

Program Area

New Programmed Area Name

PUBLIC SAFETY PROGRAM

#### Interview Room - continued

#### **Electrical**

- 1 light switch w/ "in use" light
- 1 panic device
- laptop cable

#### **Acoustics**

- partitions to extend to underside of structure
- sound batt insul. in stud partitions
- acoustic wall panels on one wall

#### Security

- standard commercial lockset
- discreet CCTV audio and video surveillance

#### Special

one-way glass to each office

#### 6.03 Equipment Storage Room

12 s.f.

#### **Furniture**

2 18" x 36" x 72" - 5 tier shelving

#### Security

standard commercial lockset

#### 7. Department Administration

#### 7.01 Administrative Assistant

120 s.f.

#### Furniture

- 1 "U" workstation with chair
- 3 four drawer lateral file cabinets
- 1 typewriter stand

#### Equipment

- 1 computer
- 1 multifunction device
- 1 telephone

#### Security

• standard commercial lockset

med Ar	ea Name	Program Area
7.02	Reprographics/Work Area	20 s.f
	Casework and Built-ins 6 lineal feet of base & upper cabinets	
	Equipment  1 multifunction printer 1 paper shredder 1 mail machine	
7.03	Future Office	120 s.f
	Furniture  1 "U" workstation  3 two drawer lateral file cabinets  2 visitor chairs	
	Casework and Built-ins 9 If open countertop (over files) 18 If wall shelving (over files)	
	Equipment 1 computer (@ workstation) 1 telephone (@ workstation)	
	Security - standard commercial lockset	
	Accessory Areas  • coat closet	
7.04	Lieutenant's Office	160 s.1
	Furniture  1 "U" workstations  3 two drawer lateral file cabinets  1 worktable with four chairs  Casework and Built-ins  9 If open countertop (over files)	

Detail Space Requirements

Public Safety

New Programmed Area Name

Program Area

#### Lieutenant's Office - continued

#### **Equipment**

- 1 computer (@ workstation)
- 1 telephone (@ workstation)

#### **Acoustics**

• sound batt insul. in stud partitions

#### Security

standard commercial lockset

#### **Accessory Areas**

coat closet

#### 7.05 Chief's Office

180 s.f.

#### General

provide direct access from exterior

#### **Furniture**

- 1 exec. desk w/ credenza
- 2 two drawer lateral files
- 2 visitor chairs

#### Casework and Built-ins

- 6 If open countertop (over files)
- 12 If wall shelving (over files)

#### **Equipment**

- 1 computer (@ workstation)
- 1 printer (@ workstation)
- 1 telephone (@ workstation)

#### **Acoustics**

- partitions to extend to underside of structure
- sound batt insul. in stud partitions

#### Security

• standard commercial lockset

#### **Accessory Areas**

large closet

nmed Ar	ea Name	Program Arec
7.06	Conference Room	320 s.f
	Furniture	
	1 conference table w/ 16 chairs	
	Casework and Built-ins	
	6 lineal feet base cabinets	
	Equipment	
	1 telephone	
	<ul><li>1 laptop/projection provision at table</li><li>1 flat panel monitor</li></ul>	
	Acoustics	
	<ul><li>partitions to extend to underside of structure</li><li>sound batt insulation in stud partitions</li></ul>	
	Security	
	standard commercial lockset	
Staff	Facilities	
8.01	Male Restroom/shower	210 s.:
	Casework and Built-ins	
	6 lineal feet open countertop	
	6 lineal feet bench	
	Plumbing	
	1 hc toilet stall	
	2 urinals	
	2 sink 2 shower	
	<ul><li>Security</li><li>standard commercial push/pull</li></ul>	

#### Public Safety

med Ar	ea Name	Program Area
.02	Male Locker Room	400 s.f.
	Equipment	
	24 2 'x 2'-6" x 6' lockers	
	4 space for future lockers	
	1 4' wet gear rack 1 shoe shine station	
	1 weapons clearing trap	
	Security	
	standard commercial push/pull	
8.03	Female Restroom/shower	160 s.f.
	Casework and Built-ins 4 lineal feet open countertop	
	3 lineal feet bench	
	Plumbing	
	1 hc toilet stall	
	1 sink 1 shower	
	3.16.1161	
	Security	
	standard commercial push/pull	
3.04	Female Locker Room	110 s.f.
	<b>Equipment</b> 6 2 'x 2'-6" x 6' lockers	
	2 space for future lockers	
	1 2' wet gear rack	
	1 shoe shine station	
	Security	
	<ul><li>Security</li><li>standard commercial push/pull</li></ul>	

Furniture

1 table(s) with four chairs

Detail Space Requirements

Public Safety

#### New Programmed Area Name

Program Area

illed Al	ed Nullie	riogiam Alea
	Break Room - Continued	
	Casework and Built-ins	
	8 If base and upper cab.	
	Equipment	
	1 refrigerator	
	1 microwave (in casework)	
	1 coffee machine (provision)	
	1 residential oven w/ cooktop	
	1 dishwasher	
	Plumbing	
	1 double bowl sink (in casework)	
3.06	Miscellaneous Male Restrooms	65 s.f.
	Consumer and Duill in	
	Casework and Built-ins	
	4 lineal feet open countertop	
	Plumbing	
	1 hc toilet stall	
	1 urinals	
	1 sink (in counter)	
	Security	
	standard commercial lockset	
3.07	Miscellaneous Female Restroom	65 s.f.
	Case work and Duill inc	
	Casework and Built-ins 4 lineal feet open countertop	
	4 illiedi leel open coomenop	
	Plumbing	
	1 hc toilet stall	
	1 toilet stall	
	1 sink (in counter)	
	Security	
	standard commercial lockset	

**Detail Space Requirements** 

#### Public Safety

Program Area New Programmed Area Name **Property and Evidence** 9.01 **Evidence Laboratory** 150 s.f. **Furniture** 3' x 6' lab tables Casework and Built-ins 24 lineal feet of base cabinets 12 lineal feet of upper cabinets Equipment 1 counter top fuming tank 1 drying cabinet 2 pass thru locker units to evidence storage 1 pass thru locker units to be refrigerated **Plumbing** double bowl sink Security proximity access control **Evidence Receiving** 9.02 40 s.f. **Furniture** 1 computer station w/printer Casework and Built-ins 5 lineal feet of base cabinet for storage of packaging materials 1 lineal feet of 6 - tier form cubbies Equipment 2 pass thru locker units - two large capacity units minimum one from hall • one unit from prisoner processing 1 refrigerated pass thru (in units above)

Security

proximity access control

9.03	Evidence Storage	400	s.f
	Furniture  4 24" x 36" x 72" metal shelving  90 lineal feet of high - density 5 - tier evidence storage sy  1 valuables safe  12 lineal feet of locked longarms racks  1 3' x 2' x 6' lockable handgun storage cabinet  1 3' x 2' x 6' vented lockable drug storage cabinet	vstem	
	Equipment 1 refrigerator		
	<ul> <li>Security</li> <li>proximity access control w/ "pin" keypad</li> <li>cctv monitoring</li> </ul>		
Prisor	ner Processing		
10.01	Sally Port (1-cruiser)	450	s.f
	General 2 12' x 12' overhead doors for each bay 1 man door		
	Plumbing  1 eye wash/emergency shower  1 floor drain per bay		
	<ul> <li>Security</li> <li>interlock all doors for one at a time operation</li> <li>cctv monitoring of interior and approach</li> <li>proximity access control in/out to Pris. Proc.</li> <li>proximity access control and remote release of OH do</li> <li>wire mesh partition to separate bay for vehicle</li> </ul>	oors fror	m
10.02	Processing Area	250	s.f
10.02	Casework and Built-ins  1 booking control workstation 1 booking bench with handcuff rings	250	:

Detail Space Requirements

#### Public Safety

New Programmed Area Name

Program Area

Equ	<i>pipment</i>
1	automated fingerprint machine
1	telephone (@ workstation)
1	telephone with two handsets for language line services
1	computer (@ workstation)
6	
1	mug shot camera on mount (@ workstation)
	static gray back drop (to match registry of motor vehicles) w/ heigh
Sec	curity
	proximity access control
	cctv monitoring of all areas
	panic devices throughout
	automatic openers for doors from sallyport
•	use least possible number of cameras to monitor booking
•	prisoner release exit
	weapons locker outside all entrances
10.03 Ho	Iding Cell 50 s.f.
Ca	sework and Built-ins
	sework and Built-ins
<b>Ca</b>	sework and Built-ins
<b>Ca</b>	sework and Built-ins lineal foot bench with cuff rail
<b>Ca</b> 8 <b>Ele</b> 1	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures
<b>Ca</b> 8 <b>Ele</b> 1	sework and Built-ins lineal foot bench with cuff rail ctrical
<b>Ca</b> 8 <b>Ele</b> 1	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity
<b>Ca</b> 8 <b>Ele</b> 1	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity minimum 10' high ceilings
<b>Ca</b> 8 <b>Ele</b> 1	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity minimum 10' high ceilings  detention grade sliding door hardware w/ cuff door
<b>Ca</b> 8 <b>Ele</b> 1	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity minimum 10' high ceilings  detention grade sliding door hardware w/ cuff door audio/video surveillance
Ca 8 Ele 1 Sec	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity minimum 10' high ceilings  detention grade sliding door hardware w/ cuff door audio/video surveillance visual observation from booking area
Ca 8 Ele 1 Sec	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity minimum 10' high ceilings  detention grade sliding door hardware w/ cuff door audio/video surveillance visual observation from booking area tamper resistant hvac grills - 1/8" holes maximum  exilyzer Area  12 s.f.
Ca 8 Ele 1 Sec •	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity minimum 10' high ceilings  detention grade sliding door hardware w/ cuff door audio/video surveillance visual observation from booking area tamper resistant hvac grills - 1/8" holes maximum  oxilyzer Area  12 s.f.
Ca 8 Ele 1 Sec	sework and Built-ins lineal foot bench with cuff rail  ctrical detention grade light fixtures  curity minimum 10' high ceilings  detention grade sliding door hardware w/ cuff door audio/video surveillance visual observation from booking area tamper resistant hvac grills - 1/8" holes maximum  exilyzer Area  12 s.f.

1 tel/data for intoxilyzer

**Detail Space Requirements** 

**Public Safety** 

#### New Programmed Area Name

Program Area

#### 10.05 Custodial Closet

20 s.f.

#### Plumbing

1 mop sink

#### **Equipment**

1 mop rack

#### Security

high security lockset

#### 10.06 Interview Room

100 s.f.

#### General

• use for bail and lawyer meetings, provide vestibule near prisoner

#### **Furniture**

1 fixed table w/ two chairs

#### **Electrical**

- 1 light switch w/ "in use" light
- 1 panic device

#### **Equipment**

1 phone discreetly located

#### Acoustics

- partitions to extend to underside of structure
- Acoustic wall panels on one wall

#### Security

- high security lockset
- discreet CCTV audio and video surveillance w/ local control

#### 10.07 Detention Restroom/shower

50 s.f.

#### **Plumbing**

- 1 handicapped accessible detention combination fixture
- 1 shower stall

Programmed Ar	ea Name	Program Are
1. Dete	ntion Facilities	
11.01	Unisex Cells (x3)	400 s.f
11.01	Offiser Gens (AG)	400 3.1
	Casework and Built-ins 1 32" x 72" x 18" concrete bunk	
	<ul><li>Equipment</li><li>telephone with long phone line</li></ul>	
	Plumbing 1 detention combination fixture	
	Electrical  1 detention grade light fixtures  • audio/video surveillance  • tamper resistant hvac grills - 1/8" holes maximum	
2. Vehi	cle Storage	
12.01	Vehicle Processing/Cruiser Maintenance	960 s.i
-	General 1 12' x 12' overhead door	
	Equipment  1 tool cabinet 1 6' work bench 1 12' tire rack 1 55 gallon oil storage tank 1 tire balancer 1 four post lift	
12.02	Mechanic's Storage	40 s.f
	Furniture 3 24" x 36" x 72" five tier shelving	
	Security	

ned Are	a Name Program A
	nistration
13.01	Conference Room 200
	<ul> <li>Description</li> <li>Seating for 8-10</li> <li>AV, TV, Screen, Lectern, etc.: All and whiteboard</li> <li>Computer/communications: Yes, Wi-Fi and cable, ceiling</li> <li>Adjacencies/comments: Combined with Police if Public Safety</li> </ul>
13.02	Chief's Office 180
	Furnishings Desk, credenza, files, table for 6, bookshelves, 4 plex at desk.  Comments/Adjacencies Secure, TV and presenting room off office Adjacent to shared bunk
13.03	Captains Office 160
	Description Captain's Office with bunk area attached Furnishings Desk, credenza, files, table for 6, bookshelves, 4 plex at desk Comments/Adjacencies Adjacent to shared bunk
13.04	Shared Bunk 144
	Description Shared bunk for Chief & Captain  Furnishings  Beds Wardrobes  Comments/Adjacencies Ramp up lighting at bunk.

ned Are	ea Name Pr	ogram	Are
13.05	Department Administrators Office	120	s.
	Description		
	Department Administrator's Office		
	Furnishings		
	Desk, cabinets, copier, printer, file cabinet.		
	Comments/Adjacencies  Chief and Cantain's offices adjacent to front entry		
	Chief and Captain's offices adjacent to front entry		
13.06	Fire Prevention / Shared Office With EMS	300	S
	Description		
	Fire Prevention, Shared Office		
	Furnishings		
	3 desks, storage drawers with flat surface for Plan review	VS.	
	Comments/Adjacencies		
	Office needs to be adjacent to entry, Public access		
13.07	Workspace	100	5
	Description		
	Base and wall cabinets, solid surface counter, mailing <b>Comments/Adjacencies</b>		
	Widened corridor to house copier, large format		
	printer/plotter, office supplies.		
13.08	Records Storage	100	
13.06	Records Storage	100	-
	Description		
	File cabinets, lateral files, table and chairs		
	Comments/Adjacencies		
	Secure		
13.09	Network/IT	200	S
	Description		
	Description  4 racks with clearance all round, marked for Verizon ar	d 911	
	HVAC	iu / i i	
	Dedicated split system, fully alarmed for heat, humidity	,	
	Comments/Adjacencies		
	Secure	•11	
	Adjacencies/comments: Manual sprinkler, combined w	ith	

Public Safety

300 s. ed, no 250 s.
250 s.
ed, no
o, all
e for
5 101
r
ee
200 s.
ed, no

Kitchen, Day Room and Bays.

	Bunk Type  • (4) singles - can be converted to doubles in future  • Separate suites, quiet and private  Furnishings  Bed, wardrobes for 4, small desk  Comments/Adjacencies  Overhead fan, individual climate controls, lighting comes up
14.05	<ul> <li>(4) singles - can be converted to doubles in future</li> <li>Separate suites, quiet and private</li> <li>Furnishings         <ul> <li>Bed, wardrobes for 4, small desk</li> </ul> </li> <li>Comments/Adjacencies</li> </ul>
14.05	<ul> <li>(4) singles - can be converted to doubles in future</li> <li>Separate suites, quiet and private</li> <li>Furnishings         <ul> <li>Bed, wardrobes for 4, small desk</li> </ul> </li> <li>Comments/Adjacencies</li> </ul>
14.05	Furnishings  Bed, wardrobes for 4, small desk  Comments/Adjacencies
14.05	Bed, wardrobes for 4, small desk  Comments/Adjacencies
14.05	Comments/Adjacencies
14.05	·
14.05	
	Baths/Showers 180
	Description
	Individual, 2 are required, unisex, sink, shower, water closet.
	Location Within bunk suite
	Comments/Adjacencies
	All tile floors and walls, floor drain, solid surface countertop,
14.06	Lockers 250
	Description
	Separate rooms for call responders.
	Location  Bunker suite
	Lockers
	40 male, 15 Female : 12" wide full height, sloped top.
	Comments/Adjacencies
	Male and female to share room, tile floor and all exposed
	walls, phenolic benches.
14.07	Housekeeping Storage 44
	Description
	Washer, dryer, folding table.  Comments/Adjacencies
	Shelving, mop and broom holder, dry goods, cleaning supplie
	sherring, mop and broom holder, ary goods, clediling supplie
14.08	Private Lobby 48

Detail Space Requirements

Public Safety

#### New Programmed Area Name

Program Area

#### 15. Apparatus/Training

#### 15.01 Apparatus Bays (12) - 6 double-deep

8,320 s.f.

#### Vehicles - total of 9

- E1 Type: Pump Length: 34' Weight: 47,000 Capacity: 4
- E2 Type: Pump Length: 40' Weight: 62,000 Capacity: 6
- E3 Type: Pump Length: 32' Weight: 53,000 Capacity: 4
- T1 Type: Ladder Length: 42' Weight: 81,000 Capacity: 6
- A1 Type: Ambulance Length: 22' Weight: 15,000 Capacity: 3
- A2 Type: Ambulance Length: 22' Weight: 15,000 Capacity: 3
- Car 3 Type: Truck Length: 18' Weight: 8,000 Capacity: 2
- Boat Type: Nautic Length: 10'
- UTV Type: Gravely Length: 8

#### Type of Bays

- Drive-thru respond in both directions
- All double deep, back to back

#### **Overhead Doors**

- 2 rows of glass.
- Front: Number: 6 Width: 14 Height: 14
- Rear: Number: 6 Width: 14 Height: 14

#### Foam

Type: 20-30 gallons/5 gallon pails.

#### Trench Drains

centered under all apparatus – to Oil/Water separator.

#### Hose Reals

Hannay wall mounted with 50' x 3/4" hose, 6 total; 3 front and 3

#### **Fume Exhaust**

Plymovent – hydraulic, all Bays, 2 fans; one for each group of six

#### Truck Fills

Overhead: One, center location.

Outdoor hydrant: Yes Location: Adjacent to Apron.

#### **Overhead Fans**

BAF or eq.

#### Electrical Drops

II Bays - 20 AMP/Drop.

#### Air Drops (2)

In-Line Air Dryer, no combination plugs.

#### Compressed Air

2 in front and 2 in rear on overhead reels.

#### Sinks

deep bowl.

Detail Space Requirements

Public Safety

New Programmed Area Name

16.

Description

Hose, fittings and nozzles

Program Area

	Apparatus Bays (12) - 6 double-deep - Continued
	Finshes Epoxy flooring, non-slip, multi-color with Back0in safety stripe Ice Machine For ambulances Comments/Adjacencies Introduce daylighting, hand towel dispenser at each overhead door pilaster.
15.02	Training Tower (Possible to be third stair) 600 s.f.
	<ul> <li>Description     Design as integral part of Bays and Connected to Mezzanine.</li> <li>Features <ul> <li>Rappelling: Yes</li> <li>Stairs: Yes</li> <li>Roof Access: Yes, reinforce parapet and roof surface at training</li> <li>Roof training: Yes</li> <li>Windows: Yes, several levels and sizes.     a. Need a window at first floor level.     b. Need window at the height of a 2-story residential building for the Hose: Yes</li> <li>Confined Space: Yes</li> <li>Sprinkler: Yes Dry: Yes     a. Use water service as training prop.</li> <li>Blackout: Yes</li> <li>Hose Drying: Yes Winch: Yes, 2 Ton.</li> <li>Other Specialized Training: Modular setup, overhead grid,</li> </ul> </li> </ul>
Firemo	atic Support
16.01	Mezzanine 1280 s.f.
	Description  Large as possible, attached to tower, share stairs.  Size  Full depth of Bays, training, possible storage, no mechanical uses.
16.02	Storage Room #01 100 s.f.

Detail Space Requirements

Public Safety

#### New Programmed Area Name

Program Area

#### Storage Room #01 - Continued

#### Location

Off the bays

#### Comments/Adjacencies

Racks, shelves and wall cabinets

#### 16.03 Work Room

120 s.f.

#### **Equipment**

- Mechanic: Town does large repairs outside of Station.
- Service: Pump service
- Workbench: Yes
- Tool storage: Yes, hand tools
- Power tools: Grinder, drill press
- Air: Yes, for tools.
- Water: Yes, deep bowl, stainless steel sink.

#### Comments/Adjacencies

Fire department needs stainless steel wall cabinets and shelves.

#### 16.04 Firematic DeCon/Laundry

168 s.f.

#### Equipment

- Sink: Yes, stainless steel with sideboard.
- Extractor: Will need to purchase. Brand: TBA
- Gear dryer: Will need to purchase Dehydrator type.
- Clothes washer: Yes, located on clean side of Station.
- Clothes Dryer: Yes located on clean side of Station.
- Drench/Eye Wash: Yes, cartridge type, proximity to work room.
- Red Bag and Sharps: Yes
- Holding Tank: No, clean at scene or hospital.
- Backboard cleaning: On occasion.
- Drench Shower: Yes
- Blood borne pathogens: Minimal, clean at hospital.

#### Comments/Adjacencies

DeCon done at hospital, NFPA 1581. Direct access to Hot Zone

Detail Space Requirements

Public Safety New Programmed Area Name Program Area **EMS Storage** 64 s.f. **Description** Restock ambulance, EMS supplies (blankets, bandages, etc.). Security Access control camera monitored Comments/Adjacencies Stainless steel shelving all around room. Locked cabinet for 16.06 Air Room (SCBA) 200 s.f. **Equipment** Sink: Yes, 4 compartment, stainless steel, NFPA 1581 Counters: 2 sideboards, mask hooks above sink

Air compressor: Yes. 3 bottles, 4,500 and 5,500 lbs.

7.4.1 Remote fill station: Yes, from compressor to Air Room

SCBA storage: All bottles Rack: 4 on a rack.

Repair: small, masks.

O2 Storage

Number of Cylinders: 16 - D and 1 - M. Look at system to hold

Comments/Adjacencies

Compressor in separate room. Will need air supply, sound

16.07 Turnout Gear 300 s.f.

**Description** 

40 required, largest locker possible, secured to walls.

Equipment

Racks: Gear Grid or Ready Rack.

Comments/Adjacencies

Over Head fans, HVAC and constant exhaust, HEPA Filter, wall

Radio/Communications Room 16.08 144 s.f.

Location

Watchroom - Adjacent to Bays with direct vision

Seating requirements

3

Door operation

Control of all 12 doors, numbered

**Equipment** 

Traffic control: No, Opticom on trucks, depends on location of

**Detail Space Requirements** 

Public Safety

#### New Programmed Area Name

Program Area

#### Radio/Communications Room - Continued

Internal paging system: Yes, and base radio.

Siren: Yes, part of ISO Rating.

Computer equipment: Yes, for each station Closed Circuit TV, Phones, Weather Station: Yes

File cabinets: Yes

Wall mounted items: Maps

Rechargeable items (plectrons): Portable radio batteries

911 tie in: No Console:

- Phones, switches, door controls, siren.

Lockable storage: No

#### **Comments/Adjacencies**

Secondary Communication Center for Dispatch, adhere to

#### 16.09 Unisex Restroom

60 s.f.

#### Plumbing

Water closet, sink, urinal, hose bib for cleaning, floor drain

#### Comments/Adjacencies

All hard washable surfaces, moisture resistant ceiling.

#### 17. Support

#### 17.01 Custodial Closets x 2

96 s.f.

#### Plumbing

1 mop sink

#### Equipment

1 mop rack

#### Security

• standard commercial lockset

#### 17.02 Mechanical Room

320 s.f.

confirm size with system selection

#### Security


standard commercial lockset

Programmed Ar	rea Name	Program Area		
17.03	Sprinkler Room	TBD s.f.		
	<ul> <li>confirm size with system selection</li> </ul>			
	Security  • standard commercial lockset			
17.04	Air Handling Equipment Room	TBD s.f.		
	Use attic or roof top			
17.05	Electrical Room	TBD s.f.		
	confirm size with system selection			
	Security - standard commercial lockset			
17.06	Emergency Electrical Room	TBD s.f.		
	confirm size with system selection			
	Security			
	<ul><li>standard commercial lockset</li><li>2-hour fire rated construction</li></ul>			
8 . Verti	cal Circulation			
18.01	Stair x 3 x 2-floors	1200 s.f.		
	assumed floor count			
18.02		120 s.f.		
18.02	hc sized cab	120 s.f.		

# Westminster, Massachusetts Site Needs Assessment

Public Safety

				1 UDIIC 3G	іСту
New Pro	ogrammed Area Name	Quan	tity	Programmed	Arec
<b>S.1</b>	Building Area				
	Building Footprint	2	story	20,165	s.f
	Future Building Growth (25% of programmed area)			5041	s.f
	Subtotal:			25,206	s.f
<b>S.2</b>	Parking Area				
	Visitor Parking	15	spaces	2,475	s.f
	Visitor Handicapped Parking	2	spaces	540	s.f
	Staff Parking	60	spaces	9,900	s.f
	Staff Handicapped Parking	2	spaces	540	s.f
	Cruiser Parking	12	spaces	1,980	s.f
	Oversize Fleet Parking	2	spaces	650	s.f
	Travel Lane Allowance			12,800	s.f
	Subtotal:			28,885	s.f
<b>S.3</b>	Site Utilities				
	Electrical Transformers			100	s.f
	Emergency Generator			350	s.f
	Antenna Tower			500	s.f
	AC Equipment			400	s.f
	Dumpsters			240	s.f
	Storm Water Retention			5,500	s.f
	Subtotal:			7,090	s.f
<b>S.4</b>	Site Amenities				
	Patio / Grill area			1,200	s.f
	Training Props	6	spaces	1,200	s.f
	Impound Lot	6	spaces	1,200	s.f
	Subtotal:			3,600	s.f
S.5	Setbacks and Green Space				
	Green space			20,900	s.f
	Setbacks			18,700	s.f
	Subtotal:			39,600	s.f
	Summation				
	Minimum useable site area			91,778	s.f
	Minimum useable site acerage			2.11	ac



## OPINION OF PROBABLE COSTS





#### Town of Westminster Public Safety Building Projected Budget Options

•	March 22 2019 New Police   New						
Marc	h 22,2019	Now Fire	New Delice				
		New Fire	New Police Station 2020	Exist. Site	Combined		
\$(000) average \$(005		Station 2020	Station 2020	2022	Facility 2020		
\$(000	) except \$/GSF						
Ne	w Construction GSF	22,346	15,527	15,527	32,264		
Re	novation GSF	0	0	11,000	0		
1	Total GSF	22,346	15,527	26,527	32,264		
Ne	w Construction \$/GSF - Current	\$ 425.00	\$ 450.00	\$ 450.00	\$ 450.00		
Re	novation \$/GSF - Current	\$ -	\$ -	\$ -	\$ -		
	w Construction \$/GSF - Escalated	\$ 477.50	\$ 505.60	\$ 505.60	\$ 505.60		
	novation \$/GSF - Escalated	\$ -	\$ -	\$ -	\$ -		
	tal Construction w/ site \$/GSF	\$ 57.23	\$ 60.40	\$ 56.26	\$ 60.41		
T	otal Project \$/GSF	\$ 718.89	\$ 787.12	\$ 508.63	\$ 764.10		
I.	Building Construction				I		
A.	New Building Construction	\$ 9,497.1	\$ 6,987.2	\$ 6,987.2	\$ 14,518.8		
В.	Existing Building Renovations	ψ 3,437.1	ψ 0,307.2	Ψ 0,307.2	Ψ 14,010.0		
<u> </u>	Total Building Construction	9,497.1	6,987.2	6,987.2	14,518.8		
II.	Related Construction	3,437.1	0,307.2	0,307.2	14,010.0		
Α.	Sitework	850.0	600.0	700.0	1,250.0		
1	Site Prep.	included	included	included	included		
2	Drives, Paths & Plazas	included	included	included	included		
3	Parking	included	included	included	included		
4	Site Improvements	included	included	included	included		
5	Landscape & Planting	included	included	included	included		
6	Building Demolition	-	-	125.0	-		
7	Wetlands Mitigation	_	n/a	n/a	n/a		
B.	Site Utility Systems	included	included	included	included		
1	Water & Fire Protection	included	included	included	included		
2	Sanitary Sewer	included	included	included	included		
3	Storm Sewer	included	included	included	included		
4	Electric	included	included	included	included		
5	Data & Communications	included	included	included	included		
6	Site Lighting	included	included	included	included		
7	Gas	included	included	included	included		
8	Steam	included	included	included	included		
9	Chilled Water	included	included	included	included		
C.	Hazardous Materials	Not Included	Not Included	Not Included	Not Included		
	Total Related Construction	850.0	600.0	825.0	1,250.0		
	SubTotal Construction - Current	\$ 10,347.1	\$ 7,587.2	\$ 7,812.2	\$ 15,768.8		
III	Escalation (2021 Completion)	1,278.9	937.8		1,949.0		
	Total Construction - Escalated	\$ 11,626.0	\$ 8,525.0	\$ 9,304.5	\$ 17,717.8		
IV.	Furniture, Fixtures & Equipment (FF		,	,			
Α.	Loose Furnishings	147.0	196.0	196.0	315.0		
B.	Program Related Equipment	75.0	100.0	100.0	145.0		
Б. С.	Data/Telecomm Equipment	150.0	200.0	200.0	300.0		
D.	Audio/Visual Equipment	30.0	50.0	50.0	65.0		
E.	Security	40.0	50.0 50.0	50.0	70.0		
F.	Specialty Signage	10.0	10.0	10.0	15.0		
	Total FF & E	452.0	606.0	606.0	910.0		
V.	Fees and Expenses	702.0	000.0	000.0	310.0		
Α.	Fees						
1	Existing Cond & Space Program	Not Included	Not Included	Not Included	Not Included		
2	Architect	1,166.0	913.1	991.1	1,958.0		
a	0	w/ architect	w/ architect	w/ architect	w/ architect		
b		w/ architect	w/ architect	w/ architect	w/ architect		
0		w/ architect	w/ architect	w/ architect	w/ architect		
d		w/ architect	w/ architect				
'	2 2a. (a. 5a. 6a. 6a. 6a. 6a. 6a. 6a. 6a. 6a. 6a. 6						


# Town of Westminster Public Safety Building Projected Budget Options

Projected Budget Options						
March 22,2019				New Police	New	
		New Fire	New Police	Exist. Site	Combined	
		Station 2020	Station 2020	2022	Facility 2020	
\$(000)	except \$/GSF					
е	Interior/Furniture Designer	w/ architect	w/ architect	w/ architect	w/ architect	
f	<del>-</del>	w/ architect	w/ architect	w/ architect	w/ architect	
g	Lighting	w/ architect	w/ architect	w/ architect	w/ architect	
h		w/ architect	w/ architect	w/ architect	w/ architect	
l i	Signage	w/ architect	w/ architect	w/ architect	w/ architect	
j	Referendum Services	w/ architect	w/ architect	w/ architect	w/ architect	
k	LEED Designer	w/ architect	w/ architect	w/ architect	w/ architect	
l.		w/ architect	w/ architect	w/ architect	w/ architect	
3	Special Consultants					
а	· · · · · · · · · · · · · · · · · · ·	Not Included	Not Included	35.0	Not Included	
b		w/ architect	w/ architect	w/ architect	w/ architect	
С		w/ architect	w/ architect	w/ architect	w/ architect	
d		35.0	35.0	45.0	35.0	
e		-	-	-	-	
f		_	_	_	_	
g		_	_	_	_	
h		w/ architect	w/ architect	w/ architect	w/ architect	
4	Project Management	581.3	426.3	465.2	750.0	
5	Building Commissioning	47.5	34.9	34.9	50.0	
6	Owner's Cost Estimator	-	-	-	32.0	
7	Owner's Legal Fees	15.0	15.0	15.0	15.0	
8	Site Survey	10.0	10.0	10.0	10.0	
9	Utility Assessment	50.0	50.0	20.0	50.0	
	Sub-total Fees	1,904.8	1,484.3	1,616.2	2,900.0	
В.	Expenses	1,000	1,10110	1,0101	_,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
1	Owner's Insurance	17.4	12.8	35.0	26.6	
2	Permits	Not Included	Not Included	Not Included	Not Included	
3	Printing	12.0	12.0	12.0	12.0	
4	Construction Utilities Use	w/ Constr	w/ Constr	w/ Constr	w/ Constr	
5	Site Borings	w/ GeoTech	w/ GeoTech	w/ GeoTech	w/ GeoTech	
6	Materials Testing	50.0	42.6	25.0	50.0	
7	Special Inspections	-	-	-	-	
8	Consultant Reimbursables	25.0	25.0	25.0	25.0	
9	Moving/Relocation	25.0	40.0	80.0	50.0	
10	Physical Plant Expenses	-	-	-	-	
11	Misc. Expenses	25.0	25.0	25.0	25.0	
12	Advertising	5.0	5.0	5.0	5.0	
13	Temporary Space/Operations	-	-	180.0	-	
14	Financing Costs/Bond Origination	50.0	50.0	50.0	70.0	
15	Site Acquisition	N/A	N/A	N/A	N/A	
	Sub-total Expenses	209.4	212.4	437.0	263.6	
	Total Fees and Expenses	2,114.2	1,696.7	2,053.2	3,163.6	
٧.	Contingency	, :-	,	,	.,	
A.	Construction	1,162.6	852.5	930.5	1,771.8	
В.	Owner's Project	709.6	541.4	598.2	1,089.6	
<u> </u>	Total Contingency	1,872.2	1,393.9	1,528.7	2,861.4	
<del></del>	Total Project	\$ 16,064.4	\$ 12,221.6	\$ 13,492.4	\$ 24,652.8	
		W   10,007.4				

Colliers PMNE 67 Hunt St.

# Public Safety Design & Construction Options Westminster, MA

Westminster, Town of
Westminster , MA
Public Safety Bldg Committee



## SUMMARY OF RESULTS





#### Structural

The current structure is deficient for this building type. Public Safety Facilities are considered Essential Service Facilities and have an increased wind and seismic load requirement over other municipal buildings. As such, numerous structural upgrades will be required should this building be part of a renovation / addition. The existing roof structure is assumed to be designed for a snow load of 35 psf. The current building code for this building type requires a snow load of 50.4 psf. This would likely require a full replacement of the entire roof structure. Additionally, most of the CMU (Concrete Masonry Unit) walls are not seismically braced to the structure reducing the buildings lateral load capacity. For wood framed walls, many of the existing are acting as shear walls. If more than 10% of these are altered than additional reinforcing will need to be installed.

#### **Architectural**

The current site and building will require significant upgrades and renovations in order to create a new, code compliant facility.

The concerns with the site include, flooding from the adjacent stream, a high water table (+/-5'-0" below grade), and a sub-surface soil condition that may result in inadequate bearing capacity for any additions. Whether or not this building is renovated or replaced these concerns will need to be addressed. To mitigate flooding risk the site should be elevated by several feet. Additionally it would be recommended that a retaining wall be installed to harden the banks of the steam to prevent erosion damage to the site and future breaches of the bank. The high water table and presence of organic material between current grade and -8'-0"+/- below grade will require a detailed geotechnical analysis, which is likely to recommend either driven piles, or a combination of rammed aggregate piers and grouted aggregate piers to increase site bearing capacity and soil stabilization.

Many of the buildings exterior finishes will need to be replaced within the next few years if the structure is to be preserved. In particular, the siding and the low slope EPDM roof require immediate attention to prevent interior water damage.

The interior of the building has several concerns that will need to be addressed. First, a HazMat review will need to be conducted to determine the extent of abatement that will be required. Based on the 1995 drawings it is assumed that the building contains ACM(Asbestos Containing material). It has not been confirmed if additional hazardous materials are present at this time.

Many of the room layouts do not currently work with the departments use, and have several ADA (Americans with Disabilities Act) violations. As noted in the structural review, if many of the walls are modified then additional structural bracing will be required. Additionally, the thermal envelope is significantly out of compliance with the current energy code. However, as noted in the structural review, this cannot be achieved without replacing the roof structure as the snow load cannot be increased as currently designed.

Significant modifications would also be required to bring this facility up to current standards for Police, Fire and Dispatch facilities. It is also noted that this construction type will not allow for this building to be compliant with NFPA 1221, which is the standard for emergency services communications facilities. Current separations between the apparatus bays and the rest of the building are limited and may be resulting in cross contamination of hazardous materials that are brought in by fire fighters on their gear when they return form a call. This may pose a potential health risk to the department.

#### **MEP Systems**

Many of the buildings mechanical systems were installed during the 1995 renovation. Several components have been replaced recently, but most of the systems installed in 1995 will need to be replaced with the renovation. If the building is not renovated then these systems will likely need to be replaced over the next 5 years.

Currently, portions of the communications equipment servers are housed in the mechanical room causing heating and cooling conflicts. These functions will need to be separated. Also, the current building has limited air conditioning. Lighting is currently limited to T8 lamps. It is recommended that these be replaced with LED lighting in order to have the building in compliance with the energy code.

#### **New Facility Costs**

Based on the programs that were developed an opinion of probable costs for each facility was prepared. To these construction costs escalation was accounted for based on the different assumed construction schedules for each facility, as well as soft costs for project development. These options were estimated to the assumed mid-point of construction.

Option 1 - New Fire Station on a new site, year 2020, for a cost of \$16,064,400

Option 2 - New Police Station on a new site, year 2020, for a cost of \$12,221,600

Option 3 - New Police Station on the existing site, year 2022, for a cost of \$13,492,400

Option 4 - New Public Safety on a new site, year 2020, for a cost of \$24,652,800

#### CONCLUSION

In summary, there are numerous significant deficiencies with this building as designed for an essential services facility. Major structural, thermal envelope, and mechanical systems will need to be upgraded in order for this building to comply with the current codes, and standards that govern this type of facility.

It is the recommendation of this study that the amount of upgrades required to have this building be functional and code compliant are too significant for a renovation to be feasible. It would be less costly, and likely will result in a better performing building for the Town of Westminster if this building is either demolished and a new building is constructed in its place, or a new Public Safety Facility be constructed on a different site.

